

Site Visit Report Form

A. BASIC DATA

(Trigon staff shall complete this field trip report within 48 hours after returning from the field and ensure that it is sent properly distributed within 72 hours after leaving the construction site)

Program (JSEP or SKEP):	SKEP PHASE: III PACKAGE: 2
School Name:	Thahr Al Sarow Basic Boys School
Supervisory Engineer (SE) Name:	Medanat
Construction Contractor (CC) Name:	Dijlah Contracting Co.
Date and Time of Field Trip:	June 21,2021
Date of Report:	June 24,2021
Weather During Visit	Sunny, 32 Degrees
Prepared By:	Mohammad Sami Ali-Ahmad CMTO/Trigon
Submitted By:	Osama Obeid CMTO/Trigon

Purpose of Visit

General Site Inspection (Quality)

Corrective Action (CA) Review Report Health, Safety & Environment (HSE) Site Meeting Substantial Completion Inspection

First Hand-over Inspection Second Hand-over Inspection OTHER (list below)

Personnel on Trip

No.	Name	Title	Agency
I	Mohammad Sami Ali-Ahmad	Intern Civil Engineer	CMTO/Trigon
2	Hanan Al Karmi	Reports & Data Manager	CMTO/Trigon
3			

Personnel at Site (if a site meeting or a final inspection, use attachment to list other participants)

No.	Name	Title	Agency
I	Sawsan Al Yousef	Resident Engineer	Medanat
2	Ala'a Oleimat	Site Engineer	Medanat
3	Ghaith Otoom	Fresh Graduate	Medanat
4	Amer Al Yousef	Project Manager	Dijlah Contracting Co.
5	Abdemalek Al Husban	Site Engineer	Dijlah Contracting Co.



6	Moayad Abu Irshaid	Quantities Surveyor	Dijlah Contracting Co.
7	Moheeb Whaidi	HSE Engineer	Dijlah Contracting Co.
8	Ahmad Abdelhadi	Safety Officer	Dijlah Contracting Co.

B. QUALITY, SCHEDULE AND H&S FINDINGS CHECKLIST

(For any "No" answer in this section, the Observer shall provide a narrative explanation in Section C. of this Report including corrective action requested) **NA-Not Applicable, DC-Didn't Check**

		Construction Contractor	Supervisory Engineer
<u>Site Doc</u>	umentation		
Ι.	Drawings and Specifications on site? (Y/N)	Y	Y
2.	CC Safety Plan on site? (Y/N)	Y	Y
3.	CC QC Plan on site? (Y/N)	Y	Y
4.	Shop Drawings up to date? (Y/N)	Y	Y
5.	Request for Information/Inspection up to date? (Y/N)	Y	Y
6.	Sampling and Testing Tracking Log? (Y/N)	Y	Y
7.	Hard copy files neat and up to date? (Y/N)	Y	Y
8.	Inspector's Daily Journal up to date? (Y/N)	Y	Y
9.	Non-Conformance Report up to date? (Y/N)	Y	Y
<u>Schedule</u>			
	. SE has up to date CC Schedule on site? (Y/N) . CC has up to date CC Schedule on site? (Y/N)	Y	Y
Exit Obs	ervation		

- 12. What time does CC start work each morning on average?
- 13. What time does CC stop work each day on average?
- 14. What is the average # of working hours each day?

7:00 AM 4:00 PM 8 Hours (1 Hour Break)

C. DESCRIPTION OF FINDINGS

(State if fact or opinion. Use attachments, maps, sketches if necessary)

A. Site Documentation

Α.

Β.

C.

• All SE's and CC's site documents were available, neat, organized and up to date



B. Health, Safety & Environment (HSE)

- Site is well secured and a proper gate has been installed to secure the construction area in addition to steel fence
- COVID-19 precautions taken at entrance
- Visitors' log at entrance
- Not all workers had full PPE gear on
- Falling hazard at the 2nd part of slab work area, the work area must be protected to avoid safety incidents

C. General Quality Observations

- Preparation for placing the 2nd part of final slab works is ongoing, the CC must comply with specifications to ensure the quality of slab
- Installing cement blocks is ongoing, the CC must use skilled workers to ensure the quality of installation is as per specifications
- Needs more attention on covering construction materials
- Concrete roughness and segregation were noticed, but minor and minimal
- As a good practice, the CC is using a steel container to mix cement to ensure the W/C ratio
- At this stage, quality of workmanship is acceptable and works seemed to be carried out as per specifications, the CC and SE must work together to provide the best possible quality

D. Schedule

- Actual Physical Progress: **37%**
- Planned Physical Progress: 40%
- Progress Variance: 3%
- Contract Time Lapsed: **52%**
- Average Number of Workers at Site During the Past Week: **30 workers/day**
- Construction works are **behind** schedule
- The CC must **deploy** more manpower to avoid more progress delays and tries to catch up with the schedule as much as possible
- During the site visit, the number of workers at site was very low, the CC can work on multiple places at the site

E. Status of Utility connections / other outstanding issue

I. <u>Water Supply</u>: Not connected



- 2. <u>Wastewater</u>: Not connected
- 3. <u>Electricity</u>: Not connected
- 4. Other Issue:

ATTACHMENTS – as marked below

- I. QUALITY CHECKLIST
- 2. MEETINGS / INSPECTION MINUTES
- 3. HEALTH, SAFETY & EVIRONMENT ATTACHMENT



E. PHOTOS



FIGURE #01:

Project ID sign on site

Photo credit: Mohammad Sami Trigon/CMTO







FIGURE #02&03:

The proposed school consists of five floor building, with an internal area of 4615.0 m2 and external area of 2827.0 m2, in addition to all related site works

Photo credit: Mohammad Sami Trigon/CMTO







FIGURE #04&05:

Installation of cement block walls is ongoing

Photo credit: Mohammad Sami Trigon/CMTO





FIGURE #06:

Installation of cement block walls is ongoing

Photo credit: Mohammad Sami Trigon/CMTO

June 21,2021

FIGURE #07:

Minor roughness and segregation were noticed

Photo credit: Mohammad Sami Trigon/CMTO









Minor roughness and segregation were noticed

Photo credit: Mohammad Sami Trigon/CMTO

June 21,2021



The CC is using a steel container to ensure W/C ratio

Photo credit: Mohammad Sami Trigon/CMTO







FIGURE #10:

Construction works of boundary wall

Photo credit: Mohammad Sami Trigon/CMTO

June 21,2021



Construction works of boundary wall is completed

Photo credit: Mohammad Sami Trigon/CMTO









FIGURE #12&13:

Preparation for placing the 2nd part of final slab is ongoing, also, the CC must protect the working area to ensure the safety of workers

Photo credit: Mohammad Sami Trigon/CMTO







FIGURE #14&15:

1st and 2nd part of final slab, placing the 1st part is completed

Photo credit: Mohammad Sami Trigon/CMTO





FIGURE #16:

The site obstacle is not solved officially yet and still causing progress delays

Photo credit: Mohammad Sami Trigon/CMTO

June 21,2021

FIGURE #17:

Preparation for placing the janitor room's slab

Photo credit: Mohammad Sami Trigon/CMTO








FIGURE #18:

Needs more attention on covering construction materials

Photo credit: Mohammad Sami Trigon/CMTO

June 21,2021



FIGURE #19:

Needs more attention on covering construction materials

Photo credit: Mohammad Sami Trigon/CMTO





FIGURE #20:

CMTO/Trigon, SE's staff and CC's staff after the site tour

Photo credit: Mohammad Sami Trigon/CMTO

June 21,2021



FIGURE #21:

COVID-19 precautions at entrance

Photo credit: Mohammad Sami Trigon/CMTO





FIGURE #22:

Site gate and warning signs

Photo credit: Mohammad Sami Trigon/CMTO



Trigon Quality Field Trip Report Attachment #I

		Date:	June 21,2021	
	School	Name:	Thahr Al Sarow Basic Boys School	
		ocation:	Jerash	
		ackage		
		ared by:		
	Prepa		Mohammad Sami Ali-Ahmad CMTO/Trigon	
#	Task / Activity	Observ- ations (Y/N)	Findings	Recommendations / Corrective Actions
. Excavation				
. Backfilling				
. SubStructural, Co	oncrete,Foundations			
1 Steel Bar				
2 Footings				
3 Ground beams	5			
4 Tie beams				
5 Column neck				
6 Column				
7 waterproofing(Insulation)			
8 Slab on grade				
	Concrete,Masonry works			
1 Columns				
2 Beams				
3 Slabs		Y	Minimal segregation were noticed	Must be repaired with special approved materials
4 Roof				
4 Roof 5 Hollow Concre	ete Block (internal)			
4 Roof5 Hollow Concre6 Hollow Concre	ete Block (internal) ete Block (external)			
4 Roof5 Hollow Concre6 Hollow Concre7 C-Channel	ete Block (external)			
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 	ete Block (external) al Stones			
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 	ete Block (external) al Stones uits/ sleeves			
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe 	ete Block (external) al Stones uits/ sleeves			
4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe 5. Civil Works	ete Block (external) al Stones uits/ sleeves es/sleeves			
4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe Civil Works 1 Access /Gates	ete Block (external) al Stones uits/ sleeves es/sleeves			
4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe 5 Civil Works 1 Access /Gates 2 Steel Doors	ete Block (external) al Stones uits/ sleeves es/sleeves			Image:
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe 6 Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 	ate Block (external) al Stones uits/ sleeves es/sleeves s			Image: Constraint of the sector of the se
4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 4 Door's accesso	ete Block (external) al Stones uits/ sleeves es/sleeves s s ories	Image: Section of the sectio		Image: Control of the sector of the secto
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe 6 Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 4 Door's access 5 Aluminum Win 	ete Block (external) al Stones uits/ sleeves es/sleeves s s s ories ndows	Image: Section of the sectio		Image: Control of the second secon
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe 2 Steel Doors 3 Wooden Doors 4 Door's access 5 Aluminum Win 6 Window screer 	ete Block (external) al Stones uits/ sleeves es/sleeves s s s ories ndows n	Image: Constraint of the sector of		Image: Control of the second secon
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe 5 Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 4 Door's accessa 5 Aluminum Win 6 Window screer 7 Steel protectio 	ete Block (external) al Stones itts/ sleeves es/sleeves s s s ories ndows n n	Image: Constraint of the sector of		Image: Control of the second secon
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 4 Door's accessa 5 Aluminum Win 6 Window screet 7 Steel protection 8 Granite sill for 	ete Block (external) al Stones uits/ sleeves es/sleeves s s s ories ndows n n m window	Image: Constraint of the sector of		Image: Control of the second secon
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 4 Door's accesso 5 Aluminum Win 6 Window screee 7 Steel protectioo 8 Granite sill for 9 Plastering (Interview) 	ete Block (external) al Stones uits/ sleeves es/sleeves s s s ories ndows n n window ernal)	Image: Section of the sectio		Image: Control of the second secon
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 4 Door's access 5 Aluminum Win 6 Window screer 7 Steel protectioo 8 Granite sill for 9 Plastering (Inte 10 Plastering (Ext 	ete Block (external) al Stones uits/ sleeves es/sleeves s s s ories ndows n n window ernal)	Image: Constraint of the sector of		Image: Control of the second secon
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 4 Door's accessod 5 Aluminum Win 6 Window screer 7 Steel protection 8 Granite sill for 9 Plastering (Inter 10 Plastering (Ext 11 Wall Paint 	ete Block (external) al Stones uits/ sleeves es/sleeves s s s ories ndows n n window ernal)	Image: Section of the sectio		Image: Control of the second secon
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 4 Door's accessod 5 Aluminum Win 6 Window screer 7 Steel protection 8 Granite sill for 9 Plastering (Inter 10 Plastering (Ext 11 Wall Paint 12 Ceiling Paint 	ete Block (external) al Stones uits/ sleeves es/sleeves s s s ories ndows n n window ernal)	Image: Section of the sectio		Image: Provide and Provide andel Provide and Provide and Provide and Provide and Provide and Pr
 4 Roof 5 Hollow Concre 6 Hollow Concre 7 C-Channel 8 Clading Natura 9 Electrical conu 10 Mechnical pipe Civil Works 1 Access /Gates 2 Steel Doors 3 Wooden Doors 4 Door's accessa 5 Aluminum Win 6 Window screet 7 Steel protection 8 Granite sill for 	ete Block (external) al Stones uits/ sleeves es/sleeves s s ories ndows n window ernal) ternal)	Image: Section of the sectio		Image: Provide a strain of the strain of



		Observ-		
#	Task / Activity	ations	Findings	Recommendations / Corrective Actions
		(Y/N)		
17	Facades, Roof parapet	(1)1()		
18	Lab Furniture			
19	Ceiling and roof system			
20	Acoustic Ceiling			
21				
21	Facades, Roof parapet			
22				
23	PVC Carpenting			
24	Expansion joint			
20	Roof insulation (waterproofing membrane)			
20	Flashing 10 cm			
21	Cold Fluid applied for boundary walls and septic			
0.0	Cold Fluid applied for boundary walls and septic			
28	tank			
	ectrical Works			
1	Wiring - condiuts			
2	Electrical sockets			
3	Lighting fixtures			
4	Electrical Distribution Board			
5	Fire Alarm System			
	Public Address			
	Air Conditioning Units			
8	CCTV			
9	Manhole			
10	Electrical Earthing			
11	Wall Fan			
	Elevator			
13	Electrical Room			
	echanical Works			
	Rest Rooms, Toilets, WC			
2	Wash basin			
3	Wall tiles			
	Floor tiles			
	Water Mixer			
	Water Cooler			
	Water Tank			
8	Boiler			
	Heat Radiator			
	Pump			
10	HVAC System			
10	AC unit/ Calit Linite/(Moll mounted)			
12	AC unit/ Split Units(Wall mounted)			
13	Pump			
14	Drainage			
15	Submersible pump sets.			
16	Manholes, Clean-outs			
17	Fire Extinguisher			
18	Fire hose cabient			
19	Ventilation, AC Duct			
20	Emergency shower			
21	Septic Tank			



		Observ-		
#	Task / Activity	ations	Findings	Recommendations / Corrective Actions
		(Y/N)		
	ternal Works			
1	Boundary walls			
2	C-Channel Finishings			
	Fence			
4	Epoxy paint			
5	Landscaping			
	External Paint			
7	Football/ Basketball Playground			
8	Sand playground for KG			
9	Plants area			
10	Car Park/Asphalt			

Disclaimer: Trigon field trip reports include information and findings based upon those parts of the construction sites we visit. Our visits and our contract scope of work do not include Trigon to carry out first tier Quality Control/Assurance, i.e., reviewing submittals, drawings and specifications, reviewing contract compliance, or in any way carrying out close supervision of the works. Therefore our field-trip reports include cursory quality, health & safety and schedule information and its entry on our reports is intended to provide the reader only with a sense of our general observations of that part of the job site we have visited



CMTO Quality/Workmanship FTR Attachment #2

Construction Quality is carrying out work according to the Drawings and Specifications - Yes/No. This is the duty of the Contractor and the Supervisory Engineer. Quality Assurance (QA) is a check to ensure that the Contractor and Supervisory Engineer is working according to the Drawings and Specifications and observing and reporting generally on basic ongoing and/or completed construction workmanship and work quality. This report is a QA report and as such is an observational view of Contractor and Supervisory Engineer overall Quality Control management.

School Name: Thahr Al Sarow Basic Boys School Location: Jerash Program/Phase/Package: SKEP/III/2 Name of Contractor : Dijlah Contracting Co. Name of Sup. Engineer: Medanat Prepared by: Mohammad Sami Ali-Ahmad CMTO/Trigon	Date / Time of Field Trip:	June 21,2021
Program/Phase/Package: SKEP/III/2 Name of Contractor : Dijlah Contracting Co. Name of Sup. Engineer: Medanat	School Name:	Thahr Al Sarow Basic Boys School
Name of Contractor : Dijlah Contracting Co. Name of Sup. Engineer: Medanat	Location:	Jerash
Name of Sup. Engineer: Medanat	Program/Phase/Package:	SKEP/III/2
	Name of Contractor :	Dijlah Contracting Co.
Prepared by: Mohammad Sami Ali-Ahmad CMTQ/Trigon	Name of Sup. Engineer:	Medanat
	Prepared by:	Mohammad Sami Ali-Ahmad CMTO/Trigon

I. GRADE KET (C)
3 Very Goo	d\	

2 Acceptable

l Poor

3

2. General Observations : (Yes = 2 / No = 1)

#	General QC Management Observations (33% of Grade)	STATUS	GRADE
I	QC Plan Approved By Supervising Engineer	Yes	2
2	QC Plan on-Site and Used by Construction Contractor	Yes	2
3	Approved Schedule On Site	Yes	2
4	Approved Shop Drawings On Site	Yes	2
5	Approved Material Submittals On Site	Yes	2
6	Material Acceptance/Rejection Forms Used On Site	Yes	2
7	Material Acceptance/Rejection Tracking Log in Monthly Report	Yes	2
8	Hard Copy Drawings/Specifications On Site	Yes	2
9	Hard Copy Drawings Marked Up Daily to Be As-Built	Yes	2
10	Supervisory Engineer Has and Uses Specification Testing Plan	Yes	2
	Sub-Total	100%	20

2 R 3 E	Excavation and Backfilling Works Reinforced Concrete (forming, steel, placing, final result, curing)	Acceptable	2
3 E	Reinforced Concrete (forming, steel, placing, final result, curing)		
·		Acceptable	2
4 F	External Wall Façade		-
	-loor Tiles Installation		-
5 Ir	nternal Plastering		-
6 E	External Plastering		-
7 C	Doors		-
8 \	Windows		-
9 Ir	nternal Painting		-
10 E	External Painting		-
11 M	Mechanical and Plumbing (HVAC, Water Supply, Wastewater)		-
12 E	Electrical Works		-
13 E	Elevator		-
l4 Ir	nternal Wall Tiling		-
15 R	Roof Waterproof Membrane		-
16 Si	Site Works	Acceptable	2
17 P	Protection of Completed Works		-
18 P	Post Construction Cleaning		-
	Sub-Total	67%	6
	Quality Indicator Grade %	78%	