

### Site Visit Report Form

### A. BASIC DATA

(Trigon staff shall complete this field trip report within 48 hours after returning from the field and ensure that it is sent properly distributed within 72 hours after leaving the construction site)

### Program (JSEP or SKEP):

School Name: Supervisory Engineer (SE) : Construction Contractor (CC): Date and Time of Field Trip: Date of Report: Weather During Visit Prepared By: Submitted By: SKEP III Package I Hai Al Iskan Basic School for Boys Medanat Consultant Engineers Dijlah Contracting May 23,2021 May 26,2021 Sunny 24° Osama Obeid **CMTO/Trigon** Osama Obeid **CMTO/Trigon** 

### Purpose of Visit

#### **General Site Inspection (Quality)**

Corrective Action (CA) Review Report Health, Safety & Environment (HSE) Site Meeting Substantial Completion Inspection First Hand-over Inspection Second Hand-over Inspection OTHER (list below)

### Personnel on Trip

No.	Name	Title	Agency	
I.	Osama Obeid	Sr. Construction Manager	CMTO/Trigon	
2				

#### **Personnel at Site** (if a site meeting or a final inspection, use attachment to list other participants)

No.	Name	Title	Agency
I	Natheer Amareen	PM	Medanat
2	Sawsan Al Yousef	RE	Medanat
3	Ammar Gharaibeh	SE	Medanat
4	Mohammad Mbaideen	H&S Manager	Medanat
5	Mohannad Abu Irshid	General Manager	Dijlah
6	Amer Yousef	PM	Dijlah
7	Moheeb Whaidi	H&S Manager	Dijlah
8	Tharwa Melkawi	SE	Dijlah

### FTR # QR387



9	Amer Khwailah	QS	Dijlah
10	Samir Abourah	Foreman	Dijlah
11	Ayah ALAbed	Fresh Graduate	Dijlah



### **B. QUALITY, SCHEDULE AND H&S FINDINGS CHECKLIST**

(For any "No" answer in this section, the Observer shall provide a narrative explanation in Section C. of this Report including corrective action requested) **NA-Not Applicable, DC-Didn't Check** 

			Construction Contractor	Supervisory Engineer
A.	<u>Site Docı</u>	imentation		
	Ι.	Drawings and Specifications on site? (Y/N)	Y	Y
	2.	CC Safety Plan on site? (Y/N)	Y	Y
	3.	CC QC Plan on site? (Y/N)	Y	Y
	4.	Shop Drawings up to date? (Y/N)	Y	Y
	5.	Request for Information/Inspection up to date? (Y/N)	Y	Y
	6.	Sampling and Testing Tracking Log? (Y/N)	Y	Y
	7.	Hard copy files neat and up to date? (Y/N)	Y	Y
	8.	Inspector's Daily Journal up to date? (Y/N)	Y	Y
	9.	Non-Conformance Report up to date? (Y/N)	Y	Y

### B. <u>Schedule</u>

10.	SE has up to date CC Schedule on site? (Y/N)	Y	
11.	CC has up to date CC Schedule on site? (Y/N)		Y

8 Hrs

Note: The updated schedule under review

### C. Exit Observation

12. What time does CC start work each morning on average?	8:00 AM
13. What time does CC stop work each day on average?	5:00 PM

14. What is the average # of working hours each day?

### **C. DESCRIPTION OF FINDINGS**

(State if fact or opinion. Use attachments, maps, sketches if necessary)

### A. Site Documentation

• All documentations are available onsite and neatly saved

### B. Health, Safety & Environment (HSE)

- Site security: There is a gate for construction site
- There is hand gel and visitor record at entrance
- All workers had a full PPE gear on



### C. General Quality Observations

- The Basement Floor Slab is completed
- The Ground Floor Slab is completed
- The First Floor Slab is completed
- Preparation works for placing concrete for the columns of the second floor.
- 20 % of Cement block walls for the ground floor is completed
- Roughness and segregation in concrete was noticed
- Cracks was noticed in the slab of the first floor
- Poor workmanship in cement block walls was noticed on the retaining walls
- Mixing cement with water on the floor directly without using container
- Damaged Cartonal Sheets for the foundation of the retaining walls

#### D. Schedule

- 32 % of works is completed and the planned is 47%
- Ave worker/day: 19 worker/day
- The CC must increase the manpower to avoid more delays

### E. Status of Utility connections / other outstanding issue

- I. Water Supply: Not connected
- 2. Wastewater: Not connected
- 3. <u>Electricity</u>: Not connected
- 4. Other Issue:

#### **Obstacle:**

Future road issue is not resolved yet. But the CC got the instruction to shift the reinforced water tank from the boundary wall. The CC is waiting for official instructions

### **ATTACHMENTS** – as marked below

- I. QUALITY CHECKLIST
- 2. MEETINGS / INSPECTION MINUTES
- 3. HEALTH, SAFETY & EVIRONMENT ATTACHMENT



### E. PHOTOS









#### FIGURE #02 &03:

The School consists of four floors and roof with total surface area of 5400 sq.m, in addition to other site works of total surface 4520 sq.m. The basement, ground and first floor slabs are completed





### FIGURE #04&05:

The School consists of four floors and roof with total surface area of 5400 sq.m, in addition to other site works of total surface 4520 sq.m. The basement, ground and first floor slabs are completed







#### FIGURE #06&07:

Preparation works for placing concrete for the columns of the second floor







Preparation works for placing concrete for the stairwell

Photo credit: Osama Obeid CMTO/Trigon May 23, 2021

### FIGURE #09:

There is no edge protection (unsafe for workers, site staff and visitors)












#### FIGURE #11 & 12:

Roughness and segregation in concrete was noticed on walls





### FIGURE #10 & 11:

Poor workmanship was noticed in the cement block walls of the retaining walls

Damaged Cartonal Sheets must be replaced





### FIGURE #12 & 13:

The CC start building the cement block walls in the ground floor





#### FIGURE #14

Mixing the cement with water on the floor without using a container will not keep the water/cement ratio as per specs and will make the area wet under floor tiles



#### Trigon Quality Field Trip Report Attachment #I

	Da	te:	May 23,2021	
		ne:		
		on:	Jerash	
	Program / Phase / Packa	-	SKEP/III/P2	
			Osama Obeid CMTO/Trigon	
	Prepared	-	Osama Obelo CMTO/Trigon	
#	Task / Activity	Observ- ations (Y/N)	Findings	Recommendations / Corrective Actions
Excavation				
. Backfilling				
. SubStructural, Concre	ete,Foundations			
1 Steel Bar				
2 Footings				
3 Ground beams				
4 Tie beams				
5 Column neck				
6 Column				
7 waterproofing(Insu	lation)	Y	Damaged Cartonal Sheets	The defetcs must be replaced
8 Slab on grade				
. SuperStructural, Cond	crete,Masonry works			
1 Columns				
2 Beams		Ň		
3 Slabs		Y	Cracks	Must be repaired/treated with special materials
4 Roof 5 Hollow Concrete B	leal (internal)	X	Deer warkmanakin was noticed in the compart black wells of the retaining	The defease much be made and
5 Hollow Concrete B 6 Hollow Concrete B		Y	Poor workmanship was noticed in the cement block walls of the retaining	The defetcs must be replaced
7 C-Channel	lock (external)			
8 Clading Natural Sto	2005			
9 Electrical conuits/	sleeves			
10 Mechnical pipes/sl	eeves			
. Civil Works				
1 Access /Gates				
2 Steel Doors				
3 Wooden Doors				
4 Door's accessories	3			
5 Aluminum Window				
6 Window screen	-			
7 Steel protection				
8 Granite sill for wind				
9 Plastering (Interna	1)			
10 Plastering (Externa	al)			
11 Wall Paint				
12 Ceiling Paint				
<ol> <li>Wall Paint</li> <li>Ceiling Paint</li> <li>Wall tiles</li> <li>Floor tiles (Internal</li> </ol>				



		Observ-		
#	Task / Activity	ations	Findings	Recommendations / Corrective Actions
		(Y/N)		
17	Facades, Roof parapet	(1)1()		
18	Lab Furniture			
19	Ceiling and roof system			
20	Acoustic Ceiling			
21				
21	Facades, Roof parapet			
22				
23	PVC Carpenting			
24	Expansion joint			
20	Roof insulation (waterproofing membrane)			
20	Flashing 10 cm			
21	Cold Fluid applied for boundary walls and septic			
0.0	Cold Fluid applied for boundary walls and septic			
28	tank			
	ectrical Works			
1	Wiring - condiuts			
2	Electrical sockets			
3	Lighting fixtures			
4	Electrical Distribution Board			
5	Fire Alarm System			
	Public Address			
	Air Conditioning Units			
8	CCTV			
9	Manhole			
10	Electrical Earthing			
11	Wall Fan			
	Elevator			
13	Electrical Room			
	echanical Works			
	Rest Rooms, Toilets, WC			
2	Wash basin			
3	Wall tiles			
	Floor tiles			
	Water Mixer			
	Water Cooler			
	Water Tank			
8	Boiler			
	Heat Radiator			
	Pump			
10	HVAC System			
10	AC unit/ Calit Linite/(Moll mounted)			
12	AC unit/ Split Units(Wall mounted)			
13	Pump			
14	Drainage			
15	Submersible pump sets.			
16	Manholes, Clean-outs			
17	Fire Extinguisher			
18	Fire hose cabient			
19	Ventilation, AC Duct			
20	Emergency shower			
21	Septic Tank			



#	Task / Activity	Observ- ations	Findings	Recommendations / Corrective Actions
		(Y/N)		
H.E	xternal Works			
1	Boundary walls			
2	C-Channel Finishings			
	Fence			
4	Epoxy paint			
	Landscaping			
6	External Paint			
7	Football/ Basketball Playground			
8	Sand playground for KG			
9	Plants area			
10	Car Park/Asphalt			

Shortage of manpower

Disclaimer: Trigon field trip reports include information and findings based upon those parts of the construction sites we visit. Our visits and our contract scope of work do not include Trigon to carry out first tier Quality Control/Assurance, i.e., reviewing submittals, drawings and specifications, reviewing contract compliance, or in any way carrying out close supervision of the works. Therefore our field-trip reports include cursory quality, health & safety and schedule information and its entry on our reports is intended to provide the reader only with a sense of our general observations of that part of the job site we have visited



### CMTO Quality/Workmanship FTR Attachment #2

Construction Quality is carrying out work according to the Drawings and Specifications - Yes/No. This is the duty of the Contractor and the Supervisory Engineer. Quality Assurance (QA) is a check to ensure that the Contractor and Supervisory Engineer is working according to the Drawings and Specifications and observing and reporting generally on basic ongoing and/or completed construction workmanship and work quality. This report is a QA report and as such is an observational view of Contractor and Supervisory Engineer overall Quality Control management.

	Date / Time of Field Trip:	5/23/2021 11:30	
	School Name:	Hai Al Iskan Basic School for Boys	
	Location:	Jerash	
	Program/Phase/Package:	SKEP/III/P2	
	Name of Contractor	: Dijlah Contracting	
	Name of Sup. Engineers	Medanat Consultant	
	Prepared by:	: Osama Obeid	
I. GRADE KEY (Quality Observations)			
3 Very Good\		_	
2 Acceptable			
L D			

I Poor 2. General Observations : (Yes = 2 / No = 1)

#	General QC Management Observations (33% of Grad	le) <b>STATUS</b>	GRADE
I	QC Plan Approved By Supervising Engineer	Yes	2
2	QC Plan on-Site and Used by Construction Contractor	Yes	2
3	Approved Schedule On Site	Yes	2
4	Approved Shop Drawings On Site	Yes	2
5	Approved Material Submittals On Site	Yes	2
6	Material Acceptance/Rejection Forms Used On Site	Yes	2
7	Material Acceptance/Rejection Tracking Log in Monthly Report	Yes	2
8	Hard Copy Drawings/Specifications On Site	Yes	2
9	Hard Copy Drawings Marked Up Daily to Be As-Built	Yes	2
10	Supervisory Engineer Has and Uses Specification Testing Plan	Yes	2
	Sul	o-Total 100%	<b>20</b>

#	Activity Quality/Workmanship Observations (67% of Grade)	STATUS	GRADE
I	Excavation and Backfilling Works	Acceptable	2
2	Reinforced Concrete (forming, steel, placing, final result, curing)	Poor	I
3	External Wall Façade		-
4	Floor Tiles Installation		-
5	Internal Plastering		-
6	External Plastering		-
7	Doors and Windows		-
8	Mechanical and Plumbing (HVAC, Water Supply, Wastewater)		-
9	Electrical Works and Elevators		-
10	Internal Wall Tiling		-
П	Roof Waterproof Membrane		-
12	Internal and External Painting		-
13	Site Works		-
14	Protection of Completed Works		-
	Sub-Total	50%	3
	Quality Indicator Grade %	67%	
ΟΤΕ	e		

1 of 1