Quality Control Report



ConsultantWahib MedanatConsultant EngineersSite NameJumana Bint Abi Taleb Basic Mixed - MarkaPackagePackage 2ContractorDijlah Est. Construction Co.Tender No.10/2019/USAID/SKEP/3/2			Rep No. Date	QC-23 06 27 /07 / 2021
Descr	iption of Non	Corrective Action	Req	uired by / When
Co	nformance			
 Number of stones have broken edges. Gaps between stones have to be unified. Chesseling pattern has to be unified for all stones as per approved sample. Wooden wedges have to be removed from inside before 		 Broken stones have to be removed. Gaps to be rectified where possible. Stones not complying with sample has to be removed. Wedges to be removed- follow up by SE. Steel ties to be stronger and more fixing points- follow up By SE. 	The Contractor/Immediately	

Report Prepared by

Hassan Shaqbua, Supervision Quality Control Manager

Contractor's Response

The Contractor is responding partially	
Notes	

Quality Control Report Before Photos:





Remarks on the stone work as per report



Remarks on the stone work as per the report

Schools for Knowledge Economy Project SKEP III

Quality Control Report





Remarks on the stone work as per the report



Remarks on the stone work as per the report

Quality Control Report



Photos After:



Removing defected stones



Removing defected stones

Schools for Knowledge Economy Project SKEP III

Quality Control Report



Pointing on the defected stone to be removed



Pointing on the defected stone to be removed

Signature





Schools for Knowledge Economy Project SKEP III

Quality Control Report



Rectifying the fixation of stones



Rectifying the fixation of stones

Signature

