### **Quality Control Report**



Consultant	Wahib Medanat Consultant Engineers
Site Name	Um Al Dananir Basic Mixed - Balqa
Package	Package 1
Contractor	Derar Saraireh & Sons for Engineering & Contracting
Tender No.	1/2020/USAID/SKEP/3/1

Rep No.	QC-11 1	3	
Date	22	/ 11 /	2021

Description of Non Conformance	Corrective Action	Required by / When
1. Dirt and cement mortar residues	1. Clean and protect by	The Contractor/Immediately
on door frames.	appropriate sheets.	
2. Cartonal sheets protecting the	2. To be completed and	
insulation of boundary walls not completed.	organized.	
3. Water penetration appeard at	3. Remove defect, execute	
the internal walls and ceilings.	waterproofing before painting.	
4. Mixing mortar without	4. Use container.	
container.		
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
No response by the Contractor		
yet.		
Notes		-
It was observed that the		
Contractor is continuing in		
replacing defected door frames.		

**Contractor Site Engineer** 

Signature

# Quality Control Report



#### **Before Photos:**



Dirt and cement mortar residues on door frames

**Consultant Site Engineer** 

## Quality Control Report





Cartonal sheets protecting the insulation of boundary walls not completed

**Consultant Site Engineer** 

## **Quality Control Report**





Rain water gathering at the roof



Penetration of rain water through the walls

**Consultant Site Engineer** 

**Contractor Site Engineer** 

4/8

## Quality Control Report





Penetration of water at the ceilings

**Consultant Site Engineer** 

## Quality Control Report





Penetration of water at the ceilings

**Consultant Site Engineer** 

## **Quality Control Report**





Mixing mortar without container

**Consultant Site Engineer** 

**Contractor Site Engineer** 

Signature

### Quality Control Report Photos After:





Replaced door frames with the correct dimensions

**Consultant Site Engineer** 

**Contractor Site Engineer** 

8/8