

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Hay Al Iskan Basic mixed - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-21 15**
Date **6 / 12 / 2021**

| Description of Non Conformance | Corrective Action | Required by / When |
|---|--|----------------------------|
| 1. Defects in floor tiling. | 1. Replace defected tiles. | The Contractor/Immediately |
| Report Prepared by | Hassan Shaqbua, Supervision Quality Control Manager | |
| Contractor's Response | | |
| It was observed that the Contractor started with rectification of: 1. Defected stones. 2. Defected floor tiles. | | |
| Notes | | |

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos



Defected stone work



Defected porcelain floor tiles

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

2/4

1/3/2022


C:\Users\o.naddaf\Desktop\Qc-December 2021\
QC- 211506122021.xlsx

Quality Control Report

Photos After:



Starting with replacing defected stones



Replacing defected stones

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

3/4

1/3/2022

C:\Users\o.naddaf\Desktop\Qc-December 2021\
QC- 211506122021.xlsx

Quality Control Report



Removing defected porcelain floor tiles

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature