

Site Visit Report Form

A. BASIC DATA

(Trigon staff shall complete this field trip report within 48 hours after returning from the field and ensure that it is sent properly distributed within 72 hours after leaving the construction site)

SKEP PHASE: III PACKA
Hay Al Iskan Basic Mixed School
Medanat
Dijlah Contracting Co.
June 21,2021
June 24,2021
Sunny, 32 Degrees
Mohammad Sami Ali-Ahmad CMTO/Trigon
Osama Obeid CMTO/Trigon

Purpose of Visit

General Site Inspection (Quality)

Corrective Action (CA) Review Report Health, Safety & Environment (HSE) Site Meeting Substantial Completion Inspection

First Hand-over Inspection Second Hand-over Inspection OTHER (list below)

Personnel on Trip

No.	Name	Title	Agency
I	Mohammad Sami Ali-Ahmad	Intern Civil Engineer	CMTO/Trigon
2	Hanan Al Karmi	Reports & Data Manager	CMTO/Trigon
3			

Personnel at Site (if a site meeting or a final inspection, use attachment to list other participants)

No.	Name	Title	Agency
I	Sawsan Al Yousef	Resident Engineer	Medanat
2	Ammar Gharaibeh	Site Engineer	Medanat
3	Ali Nazzal	Quantities Surveyor	Medanat
4	Sarah Al Ali	Fresh Graduate	Medanat
5	Tharwah Malkawi	Site Engineer	Dijlah Contracting Co.

FTR # QR 418

PHASE: III PACKAGE: 2



6	Amer Khweileh	Quantities Surveyor	Dijlah Contracting Co.
7	Moheeb Whaidi	HSE Engineer	Dijlah Contracting Co.
8	Omar Haddad	Safety Officer	Dijlah Contracting Co.
9	Aya Al Abed	Fresh Graduate	Dijlah Contracting Co.

B. QUALITY, SCHEDULE AND H&S FINDINGS CHECKLIST

(For any "No" answer in this section, the Observer shall provide a narrative explanation in Section C. of this Report including corrective action requested) **NA-Not Applicable, DC-Didn't Check**

			Construction <u>Contractor</u>	Supervisory Engineer
Α.	<u>Site Docu</u>	<u>imentation</u>		
	L.	Drawings and Specifications on site? (Y/N)	Y	Y
	2.	CC Safety Plan on site? (Y/N)	Ý	Y
	3.	CC QC Plan on site? (Y/N)	Ý	Ŷ
	4.	Shop Drawings up to date? (Y/N)	Y	Y
	5.	Request for Information/Inspection up to date? (Y/N)	Y	Y
	6.	Sampling and Testing Tracking Log? (Y/N)	Y	Y
	7.	Hard copy files neat and up to date? (Y/N)	Y	Y
	8.	Inspector's Daily Journal up to date? (Y/N)	Y	Y
	9.	Non-Conformance Report up to date? (Y/N)	Y	Y
B.	Schedule			
D.	Scheudle			
		SE has up to date CC Schedule on site? (Y/N) CC has up to date SE Schedule on site? (Y/N)	Y	Y

C. Exit Observation

- 12. What time does CC start work each morning on average?
- 13. What time does CC stop work each day on average?
- 14. What is the average # of working hours each day?

7:00 AM 4:00 PM 8 Hours (I Hour Break)

C. DESCRIPTION OF FINDINGS

(State if fact or opinion. Use attachments, maps, sketches if necessary)

A. Site Documentation

• All SE's and CC's site documents were available, neat, organized and up to date



B. Health, Safety & Environment (HSE)

- Site is well secured and a proper gate has been installed to secure the construction area in addition to steel fence
- COVID-19 precautions taken at entrance
- Visitors' log at entrance
- Not all workers had full PPE gear on
- It was noticed there is a falling hazard at the 2nd part of slab work area, the work area must be protected to avoid safety incidents

C. General Quality Observations

- At this stage, quality of concrete workmanship is good, with minimal amount of segregation observed and noticed, even though, those spots must be repaired with special approved materials
- Preparation for placing the 2nd part of final slab is ongoing, placing must be done in compliance with specifications to ensure the quality of concrete is as required
- Installation of cement block walls is ongoing

D. Schedule

- Actual Physical Progress: 37%
- Planned Physical Progress: 40%
- Progress Variance: 3%
- Contract Time Lapsed: **52%**
- Average Number of Workers at Site During the Past Week: 30 workers/day
- Construction works are **behind** schedule
- The CC must **deploy** more manpower to avoid more progress delays and tries to catch up with the schedule as much as possible
- During the site visit, the number of workers at site was very low, the CC can work on multiple places at the site

E. <u>Status of Utility connections / other outstanding issue</u>

- I. <u>Water Supply</u>: Not connected
- 2. <u>Wastewater</u>: Not connected



- 3. <u>Electricity</u>: Not connected
- 4. Other Issue:

The proposed road issue is not solved yet, the CC is waiting for official instructions to shift the R/C water tank near the boundary wall

ATTACHMENTS – as marked below

- I. QUALITY CHECKLIST
- 2. MEETINGS / INSPECTION MINUTES
- 3. HEALTH, SAFETY & EVIRONMENT ATTACHMENT



E. PHOTOS

	SCUDOL
	SCHOOLS FOR A KNOWLEDGE ECONOMY PROJECT مشروع مدارس الإقتصاد المعرف
	Hav Al Jahan D Ackage2
	مدرسة حي الإسكان JERASH مدرسة حي الإسكان الأساسية المختلطة - جـرش
	الأساسية الحلطة - جسرت
	Owner : Ministry Of Education
	وزارة التربية والتعليم
	employer :
	ماحبالعمل، Ministry Of Public Works And Housing
	Founded By:
	تمريس. الوكالــةالأمريكية للتنمية الدوليـة Development (USAID) (USAID)
	Designed By :
	Engicon مركة الاستشار للمندسة
	درمه الاستثناري. وهيب مدانسات WAHIB MEDANAT
	Consultant Engineers مهندسون مستشارون
1	
11	Contractor :
	Dijlah Establishment Constr. مؤسسة دجابة للمقاولات الإنشائية Contracting Company
	Contracting company
	رقم العطاء، 10/2019/USAID/SKEP/3/2 رقم العطاء،
	Contract Number .
1	Duration Of Contract : 450 Days
1_	

FIGURE #01:

Project ID sign on site

Photo credit: Mohammad Sami Trigon/CMTO





FIGURE #02&03:

The proposed school consists of five floor building, with an internal area of 5240.0 m2 and external area of 4522.0 m2, in addition to all related site works

Photo credit: Mohammad Sami Trigon/CMTO





FIGURE #04:

Cement block walls works is ongoing

Photo credit: Mohammad Sami Trigon/CMTO

June 21,2021



FIGURE #05:

As a good practice, the CC is using a steel container to mix W/C

Photo credit: Mohammad Sami Trigon/CMTO





FIGURE #06:

Placing the 1st part of final slab is completed

Photo credit: Mohammad Sami Trigon/CMTO

June 21,2021



FIGURE #07:

Preparation for placing the 2nd part of final slab is ongoing

Photo credit: Mohammad Sami Trigon/CMTO






FIGURE #08:

Construction works for boundary wall is completed

Photo credit: Mohammad Sami Trigon/CMTO

June 21,2021



FIGURE #09:

Construction works for boundary wall is completed

Photo credit: Mohammad Sami Trigon/CMTO





FIGURE #10:

The site obstacle is not solved yet

Photo credit: Mohammad Sami Trigon/CMTO



Trigon Quality Field Trip Report Attachment #1

	Date:	June 21,2021	
	School Name:	Hay Al Iskan Basic Mixed School	
	Location:		
	Program / Phase / Package		
	Prepared by:	Mohammad Sami Ali-Ahmad CMTO/Trigon	
	Obse		
# Task / A	ctivity ation (Y/N		Recommendations / Corrective Actions
	(1)		
. Excavation			
. Backfilling			
. SubStructural, Concrete, Found	ations		
1 Steel Bar			
2 Footings			
3 Ground beams			
4 Tie beams			
5 Column neck			
6 Column			
7 waterproofing(Insulation)			
8 Slab on grade			
. SuperStructural, Concrete,Mas	onry works		
1 Columns			
2 Beams			
3 Slabs	Y	Preparation for placing concrete for the second part of the second floor	slab Placing must be done in compliance with specifications
4 Roof			
5 Hollow Concrete Block (inte	rnal)		
6 Hollow Concrete Block (exte	ernal)		
7 C-Channel			
8 Clading Natural Stones 9 Electrical conuits/ sleeves			
9 Electrical conuits/ sleeves 10 Mechnical pipes/sleeves			
. Civil Works			
1 Access /Gates			
2 Steel Doors			
3 Wooden Doors			
4 Door's accessories			
4 Door's accessories5 Aluminum Windows			
4 Door's accessories5 Aluminum Windows6 Window screen			
 4 Door's accessories 5 Aluminum Windows 6 Window screen 7 Steel protection 			
 4 Door's accessories 5 Aluminum Windows 6 Window screen 7 Steel protection 8 Granite sill for window 			
 4 Door's accessories 5 Aluminum Windows 6 Window screen 7 Steel protection 8 Granite sill for window 9 Plastering (Internal) 			
 4 Door's accessories 5 Aluminum Windows 6 Window screen 7 Steel protection 8 Granite sill for window 9 Plastering (Internal) 10 Plastering (External) 			
 4 Door's accessories 5 Aluminum Windows 6 Window screen 7 Steel protection 8 Granite sill for window 9 Plastering (Internal) 10 Plastering (External) 11 Wall Paint 			
 4 Door's accessories 5 Aluminum Windows 6 Window screen 7 Steel protection 8 Granite sill for window 9 Plastering (Internal) 10 Plastering (External) 			



		Observ-		
#	Task / Activity	ations	Findings	Recommendations / Corrective Actions
		(Y/N)		
17	Facades, Roof parapet	(1)1()		
18	Lab Furniture			
19	Ceiling and roof system			
20	Acoustic Ceiling			
21				
21	Facades, Roof parapet			
22				
23	PVC Carpenting			
24	Expansion joint			
20	Roof insulation (waterproofing membrane)			
20	Flashing 10 cm			
21	Cold Fluid applied for boundary walls and septic			
0.0	Cold Fluid applied for boundary walls and septic			
28	tank			
	ectrical Works			
1	Wiring - condiuts			
2	Electrical sockets			
3	Lighting fixtures			
4	Electrical Distribution Board			
5	Fire Alarm System			
	Public Address			
	Air Conditioning Units			
8	CCTV			
9	Manhole			
10	Electrical Earthing			
11	Wall Fan			
	Elevator			
13	Electrical Room			
	echanical Works			
	Rest Rooms, Toilets, WC			
2	Wash basin			
3	Wall tiles			
	Floor tiles			
	Water Mixer			
	Water Cooler			
	Water Tank			
8	Boiler			
	Heat Radiator			
	Pump			
10	HVAC System			
10	AC unit/ Calit Linite/(Moll mounted)			
12	AC unit/ Split Units(Wall mounted)			
13	Pump			
14	Drainage			
15	Submersible pump sets.			
16	Manholes, Clean-outs			
17	Fire Extinguisher			
18	Fire hose cabient			
19	Ventilation, AC Duct			
20	Emergency shower			
21	Septic Tank			



		Observ-		
#	Task / Activity	ations	Findings	Recommendations / Corrective Actions
		(Y/N)		
	ternal Works			
1	Boundary walls			
2	C-Channel Finishings			
	Fence			
4	Epoxy paint			
5	Landscaping			
	External Paint			
7	Football/ Basketball Playground			
8	Sand playground for KG			
9	Plants area			
10	Car Park/Asphalt			

Disclaimer: Trigon field trip reports include information and findings based upon those parts of the construction sites we visit. Our visits and our contract scope of work do not include Trigon to carry out first tier Quality Control/Assurance, i.e., reviewing submittals, drawings and specifications, reviewing contract compliance, or in any way carrying out close supervision of the works. Therefore our field-trip reports include cursory quality, health & safety and schedule information and its entry on our reports is intended to provide the reader only with a sense of our general observations of that part of the job site we have visited



CMTO Quality/Workmanship FTR Attachment #2

Construction Quality is carrying out work according to the Drawings and Specifications - Yes/No. This is the duty of the Contractor and the Supervisory Engineer. Quality Assurance (QA) is a check to ensure that the Contractor and Supervisory Engineer is working according to the Drawings and Specifications and observing and reporting generally on basic ongoing and/or completed construction workmanship and work quality. This report is a QA report and as such is an observational view of Contractor and Supervisory Engineer overall Quality Control management.

Date / Time of Field Trip:	June 21,2021
School Name:	Hay Al Iskan Basic Mixed School
Location:	Jerash
Program/Phase/Package:	SKEP/III/2
Name of Contractor	: Dijlah Contracting Co.
Name of Sup. Engineer	: Medanat
Prepared by	: Mohammad Sami Ali-Ahmad CMTO/Trigon
I. GRADE KEY (Quality Observations)	

I. GRADE KET)
3 Very Go	ad\	
J Very Gu	JOU	

2 Acceptable

l Poor

3

2. General Observations : (Yes = 2 / No = 1)

#	General QC Management Observations (33% of Grade)	STATUS	GRADE
T	QC Plan Approved By Supervising Engineer	Yes	2
2	QC Plan on-Site and Used by Construction Contractor	Yes	2
3	Approved Schedule On Site	Yes	2
4	Approved Shop Drawings On Site	Yes	2
5	Approved Material Submittals On Site	Yes	2
6	Material Acceptance/Rejection Forms Used On Site	Yes	2
7	Material Acceptance/Rejection Tracking Log in Monthly Report	Yes	2
8	Hard Copy Drawings/Specifications On Site	Yes	2
9	Hard Copy Drawings Marked Up Daily to Be As-Built	Yes	2
10	Supervisory Engineer Has and Uses Specification Testing Plan	Yes	2
	Sub-Total	100%	20

#	Activity Quality/Workmanship Observations (67% of Grade)	STATUS	GRADE
I.	Excavation and Backfilling Works	Acceptable	2
2	Reinforced Concrete (forming, steel, placing, final result, curing)	Acceptable	2
3	External Wall Façade		-
4	Floor Tiles Installation		-
5	Internal Plastering		-
6	External Plastering		-
7	Doors		-
8	Windows		-
9	Internal Painting		-
10	External Painting		-
П	Mechanical and Plumbing (HVAC, Water Supply, Wastewater)		-
12	Electrical Works		-
13	Elevator		-
14	Internal Wall Tiling		-
15	Roof Waterproof Membrane		-
16	Site Works	Acceptable	2
17	Protection of Completed Works		-
18	Post Construction Cleaning		-
	Sub-Total	67% 6	
	Quality Indicator Grade %	78%	
OTE	\$		