

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Um Al Dananir Basic Mixed - Balqa**  
**Package** **Package 1**  
**Contractor** **Derar Saraireh & Sons for Engineering & Contracting**  
**Tender No.** **1/2020/USAID/SKEP/3/1**

**Rep No.** **QC-11 07**  
**Date** **15 / 06 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
<p>In some locations, walls, columns and roof external beams are not in line together. Teething were observed. The teething is expected to be within the space allocated for building stones.</p>	<p>Chipping is needed for limited locations.</p>	<p>The Contractor/Immediately</p>

**Report Prepared by** Hassan Shaqbua, Supervision Quality Control Manager

### Contractor's Response

<p>No response from the Contractor to date.</p>
---

**Notes**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature