#### Schools for Knowledge Economy Project SKEP III

### **Quality Control Report**



Consultant Wahib Medanat Consultant Engineers Rep No. QC-11 14

Site Name Um Al Dananir Basic Mixed - Balqa Date 4 / 12 / 2021

Package Package 1

Contractor Derar Saraireh & Sons for Engineering & Contracting

Tender No. 1/2020/USAID/SKEP/3/1

	Description of Non Conformance	Corrective Action	Required by / When
	1. Defects in floor tiling.	1. Removal/Replacing the whole tiles.	The Contractor/Immediately
	Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
	Contractor's Response		
	It was observed that the Contractor rectified the following: 1. Starting with removal of defected floor tiles. 2. Wrapping steel door frames with protective cover.		
Notes			

Consultant Site Engineer

Contractor Site Engineer

## **Quality Control Report**

### **Before Photos:**





**Defected Porcelain floor tiles** 



Unwrapped steel door frame

Signature

## **Quality Control Report**

#### **Photos After:**





Removal of defected porcelian floor tiles

# **Quality Control Report**





Wrapped steel door frame