

Consultant	Wahib Medanat Consul	tant Engineers	Rep No.	QC-21 12
Site Name	Hay Al Iskan Basic mixed -	Jerash	Date	21 / 09 / 2021
Package	Package 2			
Contractor	Dijlah Est. Construction Co.			
Tender No.	10/2019/USAID/SKEP/3/2			
Doc	wintion of Non	Corrective Action	Pog	uirad by / Whan

Description of Non Conformance	Corrective Action	Required by / When
 Wooden wedges within the backing concrete space. Mechanical cabinets very close to the door frame. Delivered door frames have manufacturing defects. One wall tiling in sanitary unit does not comply with shop drawing. 	 Should be removed before casting. To be removed from the current location away to allow for tiling. To be replaced by Contractor. To be removed and re-tiled. 	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	-

Contractor's Response

The Contractor rectified note no. 1 and note no. 4 only

Notes

Quality Control Report Before Photos





Wooden wedges within backing concrete space



Mechanical cabinet very close to the door frame



Defected door frames







Tiled wall not complying with shop drawings

Quality Control Report Photos After:





Removing wedges out of the backing concrete space

Consultant Site Engineer



Retiled wall in accordance to the shop drawings

MAHIB MEDANAT

