

ConsultantWahib Medanat Consultant EngineersRep No.QC-13 09Site NameKhadija Bint Khwailed Basic Mixed - BalqaDate14 / 09 / 2021PackagePackage 1

Contractor Derar Saraireh & Sons for Engineering & Contracting
Tender No. 1/2020/USAID/SKEP/3/1

Description of Non Corrective Action Required by / When Conformance 1. Roughness observed at the 1. The observed parts should The Contractor/Immediately soffit of the lately casted third be rapaired using special floor slab. materials with the required 2. Wooden pieces observed process. remaining at the newly casted 2. To be removed before structural elements. plastering. 3. It was observed that the Contractor rectified three previous remarks as follows: *Block wall which was not matching with the concrete wall. *Stiffener column within a long block wall. *Process of stone building and creating stiffner columns.

> Hassan Shaqbua, Supervision Quality Control Manager

Contractor's Response

Report Prepared by

The Contractor responded to point no. 1 only.	
Notes	

Consultant Site Engineer Contractor Site Engineer



Segregation and roughness in the concrete of slab







Remaining wooden pieces at the slab

Photos After:






Repair of the segregation and roughness in the slab concrete





Repair to match the concrete wall with the block wall. (Previous Remark)





Creating a stiffner column in the block wall. (Previous Remark)





Complying with requirements in stone building (Previous Remark)



Creating stiffner columns (Previous Remark)