



SKEP III Home Office Support Site Visit Report

**WAHIB
MEDANAT**
consultant engineers

Consultant	Wahib Medanat Consultant Engineer	Rep No.	13-04072021
Contractor	Derar Saraireh & Sons for Engineering & Contracting	Tender No.	(11/2019/USAID/SKEP/3/S) Schools for a Knowledge Economy Project (SKEP) - Phase (3) Package (1, 2)
Site Name	Khadija Bint Khwailed Basic Mixed School- A Shouna Al Janoubia	Day/ Date	Sun. 04/07/2021
Duration of Project	450 Calendar Days	Total Project Budget	9,789,417.840 JD

No.	Visitors		Remarks
1	Suhair Amarin	- Project Dir./Head of Architectural Department	
2	Omar Elayan	-Senior Civil Engineer	
3	Akram Khammes	- Head of Electrical Department	
4	Marwan Sonna'a	-Head of Mechanical Department	
5	Hasan Shaqboua	-Quality Control Manager	

Visit Notes

No.	Description
1	Remarks regarding plastering were given.
2	The quality of concrete works complies with specifications.
3	Poor housekeeping, NCR was issued.
4	The Contractor was instructed to provide special container for mortar mixing used for plastering.



5	The Contractor was requested to spray water wherever needed in the site for purposes of dust control.
6	The storage status of steel reinforcement needs improvement.
7	Footing for the new wall adjacent to the existing neighbor's wall is already casted.
8	The Contractor was instructed to provide a special container for mortar mixing used for plastering works.
9	The quality of blockwork is acceptable.



Project ID
Sign on
Site





Temperature check, sterilization and signing visitors' attendance sheet at the entrance of the site, complying with Covid-19 Protocol





Footing for the new wall adjacent to the existing neighbor's wall is already casted.



Preparation for casting of second floor slab zone (B)



The quality of Blockwork is acceptable





The quality of concrete works complies with specifications



Slab formwork fixing for second floor zone (B)

Poor housekeeping, an NCR was issued



The Contractor was instructed to provide special container for mortar mixing used for plastering



The storage status of steel reinforcement needs improvement



Unsafe scaffolding/the Contractor was requested to take the necessary corrective action immediately





A tour inside the site was conducted

