Quality Control Report



Consultant Site Name Package Contractor Tender No.	Wahib Medanat Consultant Engineers Khadija Bint Khwailed Basic Mixed - Balqa Package 1 Derar Saraireh & Sons for Engineering & Contracting 1/2020/USAID/SKEP/3/1		Rep No. Date	QC-13 11 10 / 11 / 2021
Description of Non Conformance		Corrective Action	Required by / When	
 Door frames are not protected. Dimensions of sills are not complying. Installing electrical outlets at elevations is wrong. Executing expansion joint wrongly. 		 To be cleaned and protected by nylon or appropriate sheets. To be replaced. To be rectified. To be rectified. 	The Contractor/Immediately	
Report Prepared by		Hassan Shaqbua, Supervision Quality Control Manager		
Contra	ictor's Response			
No response by The Contractor.				

Notes

Consultant Site Engineer

Quality Control Report





Door frames are not protected

Consultant Site Engineer



Quality Control Report






Dimensions of sills are not complying

Consultant Site Engineer

Contractor Site Engineer

Schools for Knowledge Economy Project SKEP III Quality Control Report





Installing electrical outlets at elevations is wrong

Contractor Site Engineer

Quality Control Report





Executing expansion joint wrongly

Consultant Site Engineer

Contractor Site Engineer

Quality Control Report





The limit of the elevation needs rectification



Uncomplied backfilling full of boulders

Consultant Site Engineer

Contractor Site Engineer

Quality Control Report Photos After:





Process of rectification for the elevation limit



Finalizing the rectification for the elevation limit

Consultant Site Engineer

Schools for Knowledge Economy Project SKEP III Quality Control Report






process to re-excute the expantion joint

Consultant Site Engineer

Quality Control Report





Removal of uncomplied backfilling

Consultant Site Engineer