

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Al Khansa'a Basic Mixed - Balqa**  
**Package** **Package 1**  
**Contractor** **Derar Saraireh & Sons for Engineering & Contracting**  
**Tender No.** **1/2020/USAID/SKEP/3/1**

**Rep No.** **QC-12 10**  
**Date** **20 / 12 / 2021**

Description of Non-Conformance	Corrective Action	Required by / When
1. Defects in floor tiling. 2. Defects in window jambs/plastering work. 3. Defects/Damage in built stone. 4. Unprotected electrical conduits.	1. Removal/Replacing the whole tiles. 2. Rectify the defected and damaged stones. 3. Protect the pipes as convenient. 4. Avoid the damages due to the scaffolding and labour moving.	The Contractor/Immediately
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality Control Manager	
<b>Contractor's Response</b>		
It was observed that the Contractor rectified previous remarks. 1. Starting with removal of defected floor tiles. 2. Wrapping steel door frames with protective cover.		
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



**Defected plastering work**



**Defected stone work**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature



# Quality Control Report



**Defected stone around the pipe**



**Un-protected electrical pipes**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Defected floor tiles**



**Unwrapped steel door frames**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature



# Quality Control Report

## Photos After:



Starting with the demolition of porcelain floor tiles



Wrapped steel door frame

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

5/5

1/3/2022

C:\Users\o.naddaf\Desktop\Qc-December 2021\  
QC-121020122021.xlsx