

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Hay Al Iskan Basic mixed - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-21 14**
Date **15 / 11 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
1. Defected built stones. 2. Sills having wrong dimensions.	1. Replace. 2. Replace.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor has not responded yet to the two above mentioned defects.	
Notes	It was observed that the Contractor rectified the tiled ceramic elevation in accordance to previous instructions.	

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos



Defected built stones



Sills having wrong dimensions

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Not coordinated tiled cut-off pieces

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Coordinated tiled cut-off pieces

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature