

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Al Khansa'a Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-12 09**
Date **10 / 11 / 2021**

Description of Non-Conformance	Corrective Action	Required by / When
1. Broken window sills. 2. Mixing mortar without container.	1. Replace. 2. Use container.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor responded to point 2.	
Notes	It was observed that the Contractor responded positively to two previous remarks: 1. Shifting water cabinets. 2. Casting concrete under door frames.	

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Broken window sills

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Mixing mortar without using a container

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Door frame supported with block

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Mixing mortar by using a container

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Casting concrete under the door frames

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

6/6

11/28/2021

C:\Users\o.naddaf\Desktop\QC-November 2021\
QC-120910112021.xlsx