

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Thahr Al Sarow Basic Boys - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-22 10**
Date **15 / 11 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
1. Defected built stones. 2. Defects in accoustical plastering. 3. Unacceptable finishing of ceramic tiles at the door frames.	1. Replace. 2. Rectify. 3. Replace tiles.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	

Contractor's Response

The Contractor has not responded yet.

Notes

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

Quality Control Report

Before Photos:



Defected built stones

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in accoustical plastering

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

3/7

11/28/2021

C:\Users\o.naddaf\Desktop\QC-November 2021\
QC- 221015112021.xlsx

Quality Control Report



Unacceptable finishing of ceramic tiles at the door frames

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

4/7

11/28/2021

C:\Users\o.naddaf\Desktop\QC-November 2021\
QC- 221015112021.xlsx

Quality Control Report



Space over the fire hose cabinet needs to be casted

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

5/7

11/28/2021

C:\Users\o.naddaf\Desktop\QC-November 2021\
QC- 221015112021.xlsx

Quality Control Report

Photos After:



Steel reinforcement for lintel over the fire hose cabinet

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

6/7

11/28/2021

C:\Users\o.naddaf\Desktop\QC-November 2021\
QC- 221015112021.xlsx

Quality Control Report



Casting concrete for the lintel over the fire hose cabinet

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature