

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Jumana Bint Abi Taleb Basic Mixed - Marka**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-23 12**
Date **22 / 11 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
1. Teething observed at floor tiles. 2. Inappropriate electrical sockets location at the internal façade. 3. Inappropriate finishing of tiles at the door frames. 4. At the mock-up room, beach wood frame color-door leaf and kitchen cabinets not matching the approved color.	1. To be replaced. 2. Relocate appropriately. 3. Replace defects. 4. Replace wooden frames	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	No response yet by the Contractor.	
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Teething observed at floor tiles

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Inappropriate electrical sockets location at the internal façade

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Inappropriate finishing of tiles at the door frames

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



uncomplied beach wood frames

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Uncomplied beach wood frames

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Unprotected tiling

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

7/8

11/28/2021

C:\Users\o.naddaf\Desktop\QC-November 2021\
QC-231222112021.xlsx

Quality Control Report

Photos After:



Protected tiling

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature