Quality Control Report



Consultant Site Name Package Contractor Tender No.	Wahib Medanat Consultant Engineers Al Khansa'a Basic Mixed - Balqa Package 1 Derar Saraireh & Sons for Engineering & Contracting 1/2020/USAID/SKEP/3/1		Rep No. Date	QC-12 04 8 /06 / 2021
Description of Non- Conformance		Corrective Action	Req	uired by / When
 Walls, columns and block walls inside are not in line in some places. Stone chiselling was observed to be not the wholte area of the stone. 		 Must be recovered at the plastering stage by applying plastering layers with time gap between each layer and using mesh. This remark must be done or the stones should be replaced. 	The Cont	ractor/Immediately

Report Prepared by

Hassan Shaqbua, Supervision Quality Control Manager l

Contractor's Response

No response by the Contractor to date

Notes

Consultant Site Engineer

Contractor Site Engineer

Schools for Knowledge Economy Project SKEP III

Quality Control Report





Consultant Site Engineer

Contractor Site Engineer

Quality Control Report





Consultant Site Engineer

Contractor Site Engineer

Signature

Schools for Knowledge Economy Project SKEP III

Quality Control Report





Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Schools for Knowledge Economy Project SKEP III

Quality Control Report





Consultant Site Engineer

Contractor Site Engineer

5/5 6/27/2021 C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\1201-1202\ QC- 120408062021.xlsx

Signature

Signature