

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Thahr Al Sarow Basic Boys - Jerash**  
**Package** **Package 2**  
**Contractor** **Dijlah Est. Construction Co.**  
**Tender No.** **10/2019/USAID/SKEP/3/2**

**Rep No.** **QC-22 15**  
**Date** **19 / 04 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<ol style="list-style-type: none"> <li>1. Defected stones at elevations and entrance.</li> <li>2. Corrosion and scratches at the steel protection screens.</li> <li>3. White color dirt at the colored plastering.</li> <li>4. Defected beech wood frames for wooden doors.</li> <li>5. Broken windows sills.</li> <li>6. Defects in fixing granite cladding and coping.</li> <li>7. Unacceptable filling of the gaps around the fire hose cabinets frames.</li> <li>8. Teething in the granite tiling for landings.</li> <li>9. Defects in the casted concrete of the spectators seats.</li> </ol>	<ol style="list-style-type: none"> <li>1. Replace.</li> <li>2. Repair.</li> <li>3. Rectify.</li> <li>4. Replace.</li> <li>5. Replace.</li> <li>6. Rectify.</li> <li>7. Rectify.</li> <li>8. Rectify.</li> <li>9. Repair.</li> </ol>	<p>The Contractor/Immediately</p>
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality Control Manager	
<b>Contractor's Response</b>	No response.	
<b>Notes</b>		

Consultant Site Engineer  
Signature

Contractor Site Engineer

Signature

# Quality Control Report

## Before Photos:



**Not removed defected stones**



**Defects in the steel protection screen**

Consultant Site Engineer  
Signature

Contractor Site Engineer

Signature

2/9

4/28/2022

C:\Users\o.naddaf\Desktop\Qc-New-April\  
QC-221519042022.xlsx



# Quality Control Report



**White color appears on the external plastering**

Consultant Site Engineer  
Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Defected beech wood frames**

Consultant Site Engineer  
Signature

Contractor Site Engineer

Signature



# Quality Control Report



**Defects in installing the granite coping**

Consultant Site Engineer  
Signature

Contractor Site Engineer

Signature

5/9

4/28/2022

C:\Users\o.naddaf\Desktop\Qc-New-April\  
QC-221519042022.xlsx

# Quality Control Report



**Defects in installing the granite cladding**

Consultant Site Engineer  
Signature

Contractor Site Engineer

Signature

6/9

4/28/2022

C:\Users\o.naddaf\Desktop\Qc-New-April\  
QC-221519042022.xlsx



# Quality Control Report



**Unacceptable filling around the cabinets**



**Teething in the granite tiles at the landing**

Consultant Site Engineer  
Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Defects in concrete**

Consultant Site Engineer  
Signature

Contractor Site Engineer

Signature



# Quality Control Report

**Photos After:**



Consultant Site Engineer  
Signature

Contractor Site Engineer

Signature

9/9

4/28/2022

C:\Users\o.naddaf\Desktop\Qc-New-April\  
QC-221519042022.xlsx