

# Quality Control Report



**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Jumana Bint Abi Taleb Basic Mixed - Marka**  
**Package** **Package 2**  
**Contractor** **Dijlah Est. Construction Co.**  
**Tender No.** **10/2019/USAID/SKEP/3/2**

**Rep No.** **QC-23 20**  
**Date** **23 / 07 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<ol style="list-style-type: none"> <li>1. Defects in the painting of the horizontal pipes of the shading. Untight fabric.</li> <li>2. Parts of the steel protection screens are painted with different color.</li> <li>3. Manholes covers need cleaning from corrosion, and paint.</li> <li>4. External benches supports not colored and the stone is one piece not two.</li> <li>5. The fabric of the shading does not cover the whole area.</li> <li>6. Voids in the casted concrete of the amphitheater.</li> <li>7. Dirt at the colored plastering.</li> <li>8. Suspended ceiling at the women toilet has wrong level.</li> <li>9. Waving in the plastering/painting of the ceilings of toilets.</li> <li>10. Parts of the laboratory furniture do not comply with color scheme.</li> <li>11. Defects in the finishing around the electrical sockets.</li> <li>12. Protrusion of rainwater drainage pipe is more than required.</li> <li>13. Finishing around fire hose cabinets is not finished as agreed upon previously.</li> </ol>	<ol style="list-style-type: none"> <li>1. Repair.</li> <li>2. Paint with right color.</li> <li>3. Finish well.</li> <li>4. Rectify.</li> <li>5. Rectify.</li> <li>6. Repair.</li> <li>7. Clean.</li> <li>8. Rectify.</li> <li>9. Repair.</li> <li>10. Replace.</li> <li>11. Repair.</li> <li>12. Cut/Create water direction.</li> <li>13. Rectify.</li> </ol>	<p>The Contractor/Immediately</p>
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality	
<b>Contractor's Response</b>		
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



**Defects in the painting of the horizontal pipes of the shading. Untight fabric**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



Parts of the steel protection screens are painted with different color



Manholes covers need cleaning from corrosion, and paint

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**External benches supports not colored and the stone is one piece not two**



**The fabric of the shading does not cover the whole area**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

4/10

8/3/2022

C:\Users\o.naddaf\Desktop\Qcs-July 2022\  
QC-232023072022.xlsx

# Quality Control Report



**Voids in the casted concrete of the amphitheater**



**Dirt at the colored plastering**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Suspended ceiling at the women toilet has wrong level**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Waving in the plastering/painting of the ceilings of toilets**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Parts of the laboratory furniture do not comply with color scheme**



**Defects in the finishing around the electrical sockets**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature



# Quality Control Report



**Protrusion of rainwater drainage pipe is more than required**



**Finishing around fire hose cabinets is not finished as agreed upon previously**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

**Photos After:**



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

10/10

8/3/2022