

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Khadija Bint Khwailed Basic Mixed - Balqa**  
**Package** **Package 1**  
**Contractor** **Derar Saraireh & Sons for Engineering & Contracting**  
**Tender No.** **1/2020/USAID/SKEP/3/1**

**Rep No.** **QC-13 14**  
**Date** **16 / 02 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<p>1. Parts of stone facades have dirt appearing on the surface due to defects in other items.                      2. One door frame has wider thickness than required and resulted in extra prominences.</p>	<p>1. Clean all dirt.                      2. Replace the frame.</p>	<p>The Contractor/Without delay</p>
<p><b>Report Prepared by</b></p>	<p>Hassan Shaqbua, Supervision                      Quality Control Manager</p>	
<p><b>Contractor's Response</b></p>		
<p>The Contractor responded to point (2), but the frame is not installed yet.</p>		
<p><b>Notes</b></p>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



**Dirts on the built stones**



**Dirts on the built stones**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Door frame with wrong dimensions**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature



# Quality Control Report

## Photos After:



**Removal of door frame with wrong dimension**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

4/4

3/2/2022

C:\Users\o.naddaf\Desktop\QCs-02-2022\  
QC-131416022022.xlsx