

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Thahr Al Sarow Basic Boys - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-22 17**
Date **15 / 06 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<ol style="list-style-type: none"> 1. Defected stones at re-built stone façade. 2. Walls of entrance ramps are tiled without following approved workshop drawings. 3. Part of the main steel door does not comply with the architectural details. 4. Broken edges of granite coping at the corridors and defects in installation. 5. Defects in installation of aluminum curtain wall. 6. Granite frame of elevator observed protrusion at corners. 7. Observed waving of ceilings at the corridors. 8. Observed sharp edges of aluminum windows. 	<ol style="list-style-type: none"> 1. Dismantle the façade. 2. Remove/Submit workshop drawings then re-build. 3. Replace the wrong section. 4. Replace. 5. Relocate. 6. Repair. 7. Repair. 8. Maintain. 	The Contractor/Immediately

Report Prepared by

Hassan Shaqbua, Supervision
Quality Control Manager

Contractor's Response

The Contractor responded to remark no. (1), (4) and (7)

Notes

Contractor Site Engineer

Consultant Site Engineer
Signature

Signature

Quality Control Report

Before Photos:



Removal of defected stones



Walls at entrance/tiling not in accordance to drawing

Consultant Site Engineer
Signature

Contractor Site Engineer


Signature

2/10

7/4/2022

C:\Users\o.naddaf\Desktop\QCs-June 2022\
QC-221715062022.xlsx

Quality Control Report



Door part does not comply with architectural details

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

3/10

7/4/2022

C:\Users\o.naddaf\Desktop\QCs-June 2022\
QC-221715062022.xlsx

Quality Control Report



Broken edges of granite coping and defects in installation

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

4/10

7/4/2022

C:\Users\o.naddaf\Desktop\QCs-June 2022\
QC-221715062022.xlsx

Quality Control Report



Defects in installation of curtain wall

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

5/10

7/4/2022

C:\Users\o.naddaf\Desktop\QCs-June 2022\
QC-221715062022.xlsx

Quality Control Report



Protrusion of granite/elevator frame



Waving in ceiling

Contractor Site Engineer

Signature

Consultant Site Engineer
Signature

Quality Control Report



Sharp edges in aluminum window

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

7/10
7/4/2022

C:\Users\o.naddaf\Desktop\QCs-June 2022\
QC-221715062022.xlsx

Quality Control Report

Photos After:



Re-building of stone façade

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

8/10

7/4/2022

C:\Users\o.naddaf\Desktop\QCs-June 2022\
QC-221715062022.xlsx

Quality Control Report



Repair of coping defects

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

9/10

7/4/2022

C:\Users\o.naddaf\Desktop\QCs-June 2022\
QC-221715062022.xlsx

Quality Control Report



Repair of waving at ceiling

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

10/10

7/4/2022

C:\Users\o.naddaf\Desktop\QCs-June 2022\
QC-221715062022.xlsx