

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Thahr Al Sarow Basic Boys - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-22 12**
Date **2 / 01 / 2022**

| Description of Non Conformance | Corrective Action | Required by / When |
|--|--|----------------------------|
| 1. Steel protection grill: Corrosion layer, irregular cutting of plates and welding not finished properly. 2. Defects in built stones. 3. Water penetration at the top floor ceiling coming from the roof due to defects in waterproofing. | 1. To be rectified. 2. To be replaced. 3. To be rectified. | The Contractor/Immediately |
| Report Prepared by | Hassan Shaqbua, Supervision Quality Control Manager | |
| Contractor's Response | | |
| No response yet | | |
| Notes | | |

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

Quality Control Report

Before Photos:



Defects in the steel protection grill



Defected stones at the facades

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

2/4

2/1/2022

C:\Users\o.naddaf\Desktop\revised- QCs-01-2022\
QC- 221202012022.xlsx

Quality Control Report



Defected stones at the facades



Water penetration due to defects in the waterproofing

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

3/4

2/1/2022

C:\Users\o.naddaf\Desktop\revised- QCs-01-2022\
QC- 221202012022.xlsx

Quality Control Report

Photos After:



Consultant Site Engineer
Signature

Contractor Site Engineer
Signature