

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Hay Al Iskan Basic mixed - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-21 18**
Date **6 / 03 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Gaps between fire hose cabinets and walls and variations in levelling. 2. Verticality varied in some parts of porcelain wall tiles at the corridors. 3. Broken and unlevelled thresholds. 4. Defects in cartonal at the external walls. 5. Defects in built stones at the entrance. 6. Minor teething in porcelain floor tiles. 7. Defects in granite cladding for staircase still existing.	1. Rectify. 2. Rectify/Replace. 3. Rectify/Replace. 4. Rectify/Replace. 5. Replace. 6. Rectify/Replace. 7. Rectify/Replace.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor responded and rectified remarks no. 3 and 6	
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Defects in fire hose cabinet

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

2/7

4/3/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2101-2114\
QC-211806032022.xlsx

Quality Control Report



Defects in fire extinguisher cabinet

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in verticality of parts of porcelain wall tiles



Broken and unlevelled threshold

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in cartonal boards at boundary walls



Defects in built stones at the entrance

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Teething in porcelain floor tiles



Defects in granite cladding for staircase

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Replacing of defected threshold



Replacing of defected floor tiles

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

7/7

4/3/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2101-2114\
QC-211806032022.xlsx