



SKEP III Home Office Support Site Visit Report

**WAHIB
MEDANAT**
consultant engineers

Consultant	Wahib Medanat Consultant Engineer	Rep No.	21-22082022
Contractor	Dijlah Establishment Constr. Contracting	Tender No.	(11/2019/USAID/SKEP/3/S) Schools for a Knowledge Economy Project (SKEP) - Phase (3) Package (1, 2)
Site Name	Hay Al Iskan Basic Mixed School- Jerash	Day/ Date	Mon. 22/08/2022
Duration of Project	450 Calendar Days	Total Project Budget	8,314,983.735 JD

No.	Visitors		Remarks
1	Suhair Amarin	- Project Dir./Head of Architectural Department	
2	Hashem Abu Kwaik	- Senior Civil Engineer	
3	Akram Khammes	- Head of Electrical Department	
4	Marwan Sonna'a	- Head of Mechanical Department	
5	Hasan Shaqboua	- Quality Control Manager	

Visit Notes

No.	Description
1	The supervision team inspected the execution of shadings at the external yards.
2	The team inspected the installation of the curtain wall.
3	The team observed the executed work for the steps of the amphitheater.
4	The team observed stone works and interlock tiling at the external yards.
5	The team inspected concrete casting for SOG of the basketball court.



No.	Description
6	The team inspected painting work at the corridors and rooms.
7	The team observed the ongoing works on the suspended ceilings.



Project ID Sign
on Site





General view of the project site

(Figure: 01, 02, 03 & 04)

(Figure: 01)



(Figure: 02)



(Figure: 03)



(Figure: 04)



The supervision team conducted a site visit to inspect the progress of works

(Figure: 05)



The team inspected the installation of shadings at the external yard

(Figure: 06)



The team inspected concrete casting for SOG of the basketball court

(Figure: 07)



The team observed the executed works for the steps of the amphitheater

(Figure: 08)



Interlock tiling and stone works at the front of the school building

(Figure: 09)



(Figure: 10)

The team inspected the execution of the curtain wall

(Figure: 10 & 11)



(Figure: 11)



(Figure: 12)

Observing the progress of painting works

(Figure: 12 & 13)



(Figure: 13)



(Figure: 14)

The team discussed the status of the suspended ceilings works and aluminum windows installation

(Figure: 14 & 15)



(Figure: 15)



Inspecting laboratories furniture installation and electro-mechanical connections

(Figure: 16)



Checking tiling work at the wet areas

(Figure: 17)