

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Al Khansa'a Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-12 17**
Date **27 / 07 / 2022**

| Description of Non-Conformance | Corrective Action | Required by / When |
|---|---|----------------------------|
| 1. Plastering limit of roof parapet and flashing needs refinement. 2. Broken stone coping at the roof parapet. 3. Waving in the plastering and painting in the walls and corridors. 4. Defects in the installation of steel doors at the entrance. | 1. Rectify. 2. Replace. 3. Repair. 4. Rectify. | The Contractor/Immediately |
| Report Prepared by | Hassan Shaqbua, Supervision Quality Control Manager | |
| Contractor's Response | | |
| Notes | | |

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



The parapet plastering is not compatible with flashing



Broken stone coping

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Waving in plastering of ceiling

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in the installation of steel doors at the entrance

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature