

Consultant Wahib Medanat Consultant Engineers Rep No. QC-12 14

Site Name Al Khansa'a Basic Mixed - Balqa Date 11 / 04 / 2022

Package Package 1

**Contractor** Derar Saraireh & Sons for Engineering & Contracting

Tender No. 1/2020/USAID/SKEP/3/1

Description of Non- Conformance	Corrective Action	Required by / When
<ol> <li>Defects in the beech wood frame of the wooden doors.</li> <li>Gap between the installed extinguishers cabinets and the</li> </ol>	<ol> <li>Replace.</li> <li>.Close appropriately.</li> </ol>	The Contractor/Immediately
<ul> <li>wall.</li> <li>3. Broken stone coping at roof.</li> <li>4. Dirts at the stone facades.</li> <li>5. Hangers holding the suspended ceiling frame are not vertical.</li> <li>6. Wrong granite tiling at the staircase area- small cut off pieces appeared.</li> </ul>	<ul><li>3. Replace.</li><li>4. Clean.</li><li>5. Rectify.</li><li>6. Re-tile.</li></ul>	
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response The Contractor responded to remark no. (6).		
Notes		

Consultant Site Engineer

Contractor Site Engineer

4/28/2022
C:\Users\o.naddaf\Desktop\Qc-New-April\

QC-121411042022.xlsx

Signature Signature

### **Before Photos:**





Defects in beech wood frame

**2**/7





Gap between the cabinets and the wall



**Broken stone coping** 





Dirt at the stone facades



Dirt at the stone facades

QC-121411042022.xlsx





Hangers holding suspended ceiling are not vertical



Tiling not complying with workshop drawings

#### **Photos After:**





Removal of the granite tiling



Re-tiling complying with the workshop drawings





Completion of re-tiling