

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Thahr Al Sarow Basic Boys - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-22 16**
Date **23 / 05 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<ol style="list-style-type: none"> 1. Defects in the built stones. 2. Verticality and horizontality of built stones. 3. Broken windows sills. 4. Dimensions of the main steel doors: Dimensions of sections do not comply. 5. Small cut-off tile pieces were observed in some parts. 6. Accumulated debris and dirt at the sanitary fixtures. 7. Waving in plastering in a number of internal walls. 8. Defects in the handrails and dirt at the boundary walls. 	<ol style="list-style-type: none"> 1. Replace defected stones. 2. Replace. 3. Replace. 4. Rectify. 5. Rectify. 6. Clean and keep covered. 7. Repair. 8. Repair, clean and finish. 	<p>The Contractor/Immediately</p>
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor responded to remarks no. 1, 6 and 8.	
Notes		

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

Quality Control Report

Before Photos:



Defects in the built stones



Defects in the built stones

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

2/10

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2201-2215\
QC-221623052022.xlsx

Quality Control Report



Broken window sill

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

3/10

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2201-2215\
QC-221623052022.xlsx

Quality Control Report



Defects in the main steel doors

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

4/10

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2201-2215\
QC-221623052022.xlsx

Quality Control Report



Small cut-off ceramic tiles

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

5/10

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2201-2215\
QC-221623052022.xlsx

Quality Control Report



Accumulated debris and dirt at the sanitary fixtures



Waving in plastering

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

6/10

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2201-2215\
QC-221623052022.xlsx

Quality Control Report



Defects in the handrails and dirt at the boundary walls

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

7/10

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2201-2215\
QC-221623052022.xlsx

Quality Control Report

Photos After:



Removing defected stones



Rebuilding of stones

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

8/10

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2201-2215\
QC-221623052022.xlsx

Quality Control Report



Removal of debris and dirt from sanitary fixtures

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

9/10

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2201-2215\
QC-221623052022.xlsx

Quality Control Report



Installing and maintaining handrails

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

10/10

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2201-2215\
QC-221623052022.xlsx