

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Jumana Bint Abi Taleb Basic Mixed - Marka**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-23 15**
Date **12 / 02 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<p>1. Defected stones at the guard room, broken and not homogeneous.</p> <p>2. Teething of porcelain floor tiles at multi-purpose hall and corridor.</p> <p>3. Corrosion in the steel protection screens.</p> <p>4. Defects in aluminum/window jambs: - Jambs should be completely finished before aluminum installation. - Lab test of aluminum does not comply.</p> <p>5. Water penetration test failed for the roof of the multi-purpose hall.</p>	<p>1. Replace defected stones.</p> <p>2. Rectify.</p> <p>3. Maintain.</p> <p>4. Remove aluminum not complying with specification and maintain jambs.</p> <p>5. Check and rectify the defects.</p>	<p>The Contractor/Without delay</p>

Report Prepared by

Hassan Shaqbua, Supervision
 Quality Control Manager

Contractor's Response

- * No response to points 1, 2 and 3.
- * The Contractor reponded to point no. 4.
- * Partial response to point 5.

Notes

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Defected stones at the guard room

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

2/7

3/2/2022

C:\Users\o.naddaf\Desktop\QCs-02-2022\
QC-231512022022.xlsx

Quality Control Report



Teething at the porcelain floor tiles



Teething at the porcelain floor tiles at the corridor

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Corrosion at the steel protection screen



Defect at the window jamb

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

4/7

3/2/2022

C:\Users\o.naddaf\Desktop\QCs-02-2022\
QC-231512022022.xlsx

Quality Control Report



Leakage at the ceiling of the multi-purpose hall

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

5/7

3/2/2022

C:\Users\o.naddaf\Desktop\QCs-02-2022\
QC-231512022022.xlsx

Quality Control Report



Defects in installed aluminum window

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

6/7

3/2/2022

C:\Users\o.naddaf\Desktop\QCs-02-2022\
QC-231512022022.xlsx

Quality Control Report

Photos After:



Dismantling of defected aluminum sections

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

7/7

3/2/2022

C:\Users\o.naddaf\Desktop\QCs-02-2022\
QC-231512022022.xlsx