

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Hay Al Iskan Basic mixed - Jerash**  
**Package** **Package 2**  
**Contractor** **Dijlah Est. Construction Co.**  
**Tender No.** **10/2019/USAID/SKEP/3/2**

**Rep No.** **QC-21 19**  
**Date** **19 / 04 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. White color dirt at the colored plastering at the elevations. 2. Defected beech wood frames for the wooden doors. 3. Defects in installing the granite coping at corridors and the staircases. 4. Gaps at the connection points between inclined skirting and stairs. 5. Defects at the end point of granite and porcelain tiling at the staircase area. 6. Fixing socket covers before completing the paint.	1. Rectify. 2. Replace. 3. Rectify. 4. Rectify. 5. Rectify. 6. Fixing socket after paint.	The Contractor/Immediately
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality Control Manager	
<b>Contractor's Response</b>	The Contractor responded to remark no. (5) and no. (6).	
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



White color appears on facades



Defected wooden door frames

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Defects in installation of granite coping**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature



# Quality Control Report



**Gaps between granite pieces appeared**



**Defects in connection line between porcelain and granite**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Fixing sockets before completing the paint work**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report

## Photos After:



**Rectification of granite and porcelain tiles to match**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature