

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Jumana Bint Abi Taleb Basic Mixed - Marka**  
**Package** **Package 2**  
**Contractor** **Dijlah Est. Construction Co.**  
**Tender No.** **10/2019/USAID/SKEP/3/2**

**Rep No.** **QC-23 18**  
**Date** **14 / 05 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<ol style="list-style-type: none"> <li>1. Some parts of the colored plastering for the guard house have texture that does not comply with the sample.</li> <li>2. Observed voids at the concrete surface of the amphitheater seats.</li> <li>3. Broken stones at the floor of the building entrance.</li> <li>4. Defects in the fixing of granite coping at the corridors and staircase in relation to the plastering layers.</li> <li>5. Defects in the steel protection screens include fixation, corrosion connection point.</li> <li>6. Dirt at the colored plastering plastering of the boundary walls.</li> </ol>	<ol style="list-style-type: none"> <li>1. Repair.</li> <li>2. Repair.</li> <li>3. Replace.</li> <li>4. Repair.</li> <li>5. Repair.</li> <li>6. Clean.</li> </ol>	The Contractor/Immediately
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality Control Manager	
<b>Contractor's Response</b>	The Contractor responded to remarks 3 and 4.	
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



**Defects in the texture of colored plastering**



**Voids at the surface of the amphitheater seats**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Broken stones at the entrance floor**



**Defects in granite coping installation**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Defects in the steel protection screens**



**Dirt at the colored plastering**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

4/5

6/21/2022

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2301-2318\  
QC-231814052022.xlsx

# Quality Control Report

## Photos After:



**Rectification of stone tiles**



**Rectification of installed granite coping**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature