

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Jumana Bint Abi Taleb Basic Mixed - Marka**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-23 17**
Date **9 / 04 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. The defected stones at guard room still not replaced. 2. Defects in the beech wood frames. 3. Corrosion was observed on the radiators sections. 4. The radiators sections are scattered on the tiles. 5. Defects related to granite coping: - Gaps in the plastering behind coping. - The coping should match with the plastering and door frames. - Short pieces of granite should be avoided.	1. Replace. 2. Replace. 3. Repair. 4. Re-arrange appropriately. 5. Rectify.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor responded to remarks no. (1) and no. (5).	
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Defected stones at guard house

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

2/9

4/28/2022

C:\Users\o.naddaf\Desktop\Qc-New-April\
QC-231709042022.xlsx

Quality Control Report



Defected stone at the guard house

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in beech wood frame

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Corrosion observed on the radiators



Scattered radiators on the floor tiles

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in tiling

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in granite coping



Defects in granite coping

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Replacing defected stones at the guard house



Rectified granite tiling

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Rectified granite coping

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature