

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Um Al Dananir Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-11 16**
Date **19 / 02 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Deviation in the tiled corridor at the multi-purpose service area. 2. Humidity observed at the walls below window sills and over the skirting. 3. Corrosion in the steel protection screen. 4. Window jambs not finished to receive aluminum sections.	1. Rectify/Remove. 2. Rectify. 3. Maintain. 4. Finish before installing aluminum sections.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	No Response by the Contractor.	
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Deviation in the tiled corridor

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Humidity under the window sill



Humidity over the skirting

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Corrosion in the steel protection screens

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Window jambs not finished to receive aluminum sections

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Photos After:



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature