



Consultant	Wahib Medanat Consultant Engineer	Rep No.	11-24012022
Contractor	Derar Saraireh & Sons for Engineering & Contracting	Tender No.	(11/2019/USAID/SKEP/3/S) Schools for a Knowledge Economy Project (SKEP) - Phase (3) Package (1, 2)
Site Name	Um Al Dananir Basic Mixed School- Al Balqa	Day/ Date	Mon. 24/01/2022
Duration of Project	450 Calendar Days	Total Project Budget	9,789,417.840 JD


No.	Visitors		Remarks
1	Suhair Amarin	- Project Dir./Head of Architectural Department	
2	Hashem Abu Kwaik	- Senior Civil Engineer	
3	Akram Khammes	- Head of Electrical Department	
4	Marwan Sonna'a	- Head of Mechanical Department	
5	Hasan Shaqboua	- Quality Control Manager	

Visit Notes

No.	Description
1	The supervision team conducted general check on the executed porcelain floor tiles and observed minor tiles with teething or uneven. The Contractor was instructed to replace.
2	The supervision team discussed with the Contractor the pattern of tiling in corridors where two colors of tiles are required. It was agreed that the Contractor will prepare revised sketches showing the distribution of the two colors in the corridors and number of rooms.
3	The supervision team inspected the installed sample of steel protection screen and the aluminum frame for windows and observed that all dimensions comply with the design drawings.



4	The supervision team observed that the gap between the inside sill (marble) and the outer sill (stone) of windows is wider than required. The Contractor was requested to rectify and comply with the maximum allowed gap width as per specification (not more than 1 cm).
5	The supervision team inspected the starting of tiling work at the multi-purpose hall.
6	The supervision team inspected the installation of beads for the porcelain wall tiles and insured its acceptable quality and installation.



Project ID Sign on Site



Sterilization and signing visitors' attendance sheet at the entrance of the site, complying with Covid-19 Protocol





General view of the project site

(figure:01)



(figure:02)



(figure:03)

The supervision team conducted general check on the executed porcelain floor tiles and observed minor tiles with teething or uneven. The Contractor was instructed to replace

(figure:03 & 04)



(figure:04)



(figure:05)

The supervision team discussed with the Contractor the pattern of tiling in corridors where two colors of tiles are required. It was agreed that the Contractor will prepare revised sketches showing the distribution of the two colors in the corridors and number of rooms



(figure:05 & 06)

(figure:06)



(figure:07)

The supervision team inspected the installed sample of steel protection screen and the aluminum frame for windows and observed that all dimensions comply with the design drawings

(figure:07 & 08)



(figure:08)



(figure:09)



The supervision team observed that the gap between the inside sill (marble) and the outer sill (stone) of windows is wider than required. The Contractor was requested to rectify and comply with the maximum allowed gap width as per specification (not more than 1 cm)

(figure:09 & 10)

(figure:10)



(figure:11)

The supervision team inspected the installation of beads for the porcelain wall tiles and insured its acceptable quality and installation

(figure:11 & 12)



(figure:12)



The supervision team inspected the starting of tiling work at the multi-purpose hall

(figure:13)