

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Um Al Dananir Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-11 15**
Date **24 / 01 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<p>1. The joints between the inner window sill part and the outer window sill part are wider than required.</p>	<p>1. Window sills inside to be replaced with wider pieces to cover the difference.</p>	<p>The Contractor/Immediately</p>
<p>Report Prepared by</p>	<p>Hassan Shaqbua, Supervision Quality Control Manager</p>	
<p>Contractor's Response</p>		
<p>No Response yet</p>		
<p>Notes</p>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



The gap between the two sills

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Photos After:



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature