

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Hay Al Iskan Basic mixed - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-21 20**
Date **23 / 05 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Dimensions of the main steel doors: Dimensions of sections do not comply. 2. Dissimilarity of the end of parapets of the main staircase at the same landing. 3. Plastic accessories used for aluminum pivot windows. 4. Wooden doors not protected. 5. Defects in wooden cabinets. 6. No stiffener columns for the guard house roof parapet. 7. Wrong dimensions for the window sills.	1. Rectify as per drawings. 2. Check and repair. 3. Replace by aluminum accessories. 4. Apply appropriate protection. 5. Rectify. 6. Create stiffener columns. 7. Replace.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor responded to remarks no. 4, 6 and 7.	
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Defects in the main steel doors

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Dissimilarity at the main staircase



Dissimilarity at the main staircase

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Using plastic accessories for aluminum windows



Unprotected wooden doors

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in wooden cabinets



No stiffener columns in the parapet

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Wrong dimension for window sill

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Protection for wooden doors



Creating stiffener columns in the parapet

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Removal of defected window sill

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature