Schools for Knowledge Economy Project SKEP III

Quality Control Report



| Consultant | Wahib Medanat Consultant Engineers |
|------------|---|
| Site Name | Al Khansa'a Basic Mixed - Balqa |
| Package | Package 1 |
| Contractor | Derar Saraireh & Sons for Engineering & Contracting |
| Tender No. | 1/2020/USAID/SKEP/3/1 |

 Rep No.
 QC-12 15

 Date
 9 / 05 / 2022

| Description of Non- | Corrective Action | Required by / When |
|--|-----------------------------|----------------------------|
| Conformance | | |
| 1. Defects in the wooden cabinets, in beech wood, laminated paritions and un-vertical handles. | 1. Rectify. | The Contractor/Immediately |
| 2. Defects in fixing the granite coping at the window jamb. | 2. Rectify. | |
| | | |
| | Hassan Shaqbua, Supervision | |
| Report Prepared by | Quality Control Manager | |
| Contractor's Response | | |
| The Contractor responded | | |
| partially to remark no. 1. | | |
| Notes | _ | |
| | | |

Quality Control Report



Before Photos:



Defects in the beech frame and partitions



Defects in the beech frame and handle

Consultant Site Engineer

Contractor Site Engineer

Schools for Knowledge Economy Project SKEP III

Quality Control Report





Defects in the granite coping

Consultant Site Engineer

Contractor Site Engineer

Quality Control Report Photos After:



Removing defected parts for rectification



Removing defected parts for rectification

Consultant Site Engineer

Contractor Site Engineer

