

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** Hay Al Iskan Basic mixed - Jerash  
**Package** Package 2  
**Contractor** Dijlah Est. Construction Co.  
**Tender No.** 10/2019/USAID/SKEP/3/2

**Rep No.** QC-21 22  
**Date** 17 / 07 / 2022

Description of Non Conformance	Corrective Action	Required by / When
1. Waving in the painting of the suspended ceilings. 2. Fixation of the handrails of the staircase is insufficient. 3. Defects in the plastering and painting for a number of window jambs. 4. Defect in the installation of windows related to the external plastering which appears inside the window. 5. Incorrect installation of the electrical outlets at the laboratories. 6. Accumulation of debris inside the building and defects in tiles as a result of that. 7. Contradiction between the granite counter top for the cabinets in the kitchen with the location of electrical outlet.	1. Repair. 2. Rectify. 3. Repair. 4. Rectify. 5. Rectify. 6. Remove/Repair. 7. Relocate the outlet.	The Contractor/Immediately
<b>Report Prepared by</b>	Supervision Quality Control Manager	
<b>Contractor's Response</b>		
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



**Waviness in the painting of the suspended ceilings**



**Fixation of the handrails of the staircase is insufficient**

Consultant Site Engineer

Signature


Contractor Site Engineer

Signature

# Quality Control Report



**Defects in the plastering and painting for a number of window jambs**



**Defect in the installation of windows related to the external plastering**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Incorrect installation of the electrical outlets at the laboratories**



**Accumulation of debris inside the building and defects in tiles as a result of that**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Contradiction between the granite counter top with the location of electrical outlet**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report

**Photos After:**



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature