

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Al Khansa'a Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-12 16**
Date **25 / 06 / 2022**

Description of Non-Conformance	Corrective Action	Required by / When
1. Waving in plastering for ceilings. 2. Wrong installation of granite coping at window jambs. 3. The parapet plastering needs limitation with flashing at roof. 4. Broken stone coping.	1. Rectify. 2. Rectify. 3. Rectify. 4. Replace.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor responded to remark no. 2	
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Waving in plastering of ceiling

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Wrong installation of granite coping



The parapet plastering is not compatible with flashing

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Broken stone coping

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Rectified granite coping

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature