Quality Control Report



Consultant	Wahib Medanat Consultant Engineers
Site Name	Um Al Dananir Basic Mixed - Balqa
Package	Package 1
Contractor	Derar Saraireh & Sons for Engineering & Contracting
Tender No.	1/2020/USAID/SKEP/3/1

Rep No.	QC-11	17	
Date	9	/ 03 /	2022

Description of Non Conformance	Corrective Action	Required by / When
 Variations in the levels of the window sills. 	1. Rectify.	The Contractor/Immediately
 2. Defects in wall ceramic tiles at the wet areas/grouting/broken tiles and broken beads. 3. Defects in cutting of thresholds. 	2. Rectify/Replace.	
4. Minor teething in porcelain floor tiles.	3. Replace.	
	4. Rectify/Replace.	
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor reponded and rectified remarks no. 1, 2 and 3.		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Quality Control Report



Before Photos:



Variations in the levels of window sills



Variations in the levels of window sills

Consultant Site Engineer

Contractor Site Engineer

Quality Control Report





Defects in wall ceramic tiles

Consultant Site Engineer

Contractor Site Engineer

Schools for Knowledge Economy Project SKEP III Quality Control Report





Defects in the threshold



Teething in floor tiles

Consultant Site Engineer

Contractor Site Engineer

4/7

Quality Control Report Photos After:



Rectified window sill



Rectified ceramic tiles

Consultant Site Engineer

Contractor Site Engineer



Schools for Knowledge Economy Project SKEP III Quality Control Report





Rectified threshold

Consultant Site Engineer

Contractor Site Engineer

Quality Control Report





Rectified threshold

Consultant Site Engineer

Contractor Site Engineer