



Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name Hay Al Iskan Basic mixed - Jerash
Package Package 2
Contractor Dijlah Est. Construction Co.
Tender No. 10/2019/USAID/SKEP/3/2

Rep No. QC-21 21
Date 15 / 06 / 2022

Description of Non Conformance	Corrective Action	Required by / When
1. Rubber fixed for aluminum windows with discontinuity. 2. Part of the main steel door does not comply with architectural details. 3. Broken tiles around the radiators connection.	1. Replace the rubber. 2. Replace the wrong section. 3. Maintain neatly.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbuq, Supervision Quality Control Manager	
Contractor's Response		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Discontinuity of aluminum rubber



Door part does not comply with architectural details

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

2/4

7/4/2022

C:\Users\o.naddaf\Desktop\QCs-June 2022\
QC-212115062022.xlsx

Quality Control Report



Broken tiles around the radiator connection

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature