

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Hay Al Iskan Basic mixed - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-21 17**
Date **22 / 02 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<ol style="list-style-type: none"> 1. White color appears on the colored external plastering. 2. Defects in granite cladding for staircase are still. 3. Variation in the levels of internal windows sills. 4. Corrosion appears on the steel protection screens. 5. Defects in wall ceramic cutting adjoining the door frames. 	<ol style="list-style-type: none"> 1. Rectify. 2. Replace. 3. Rectify. 4. Rectify. 5. Replace. 	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor responded to points no. 1 and 4.	
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



White color appears on the surface of external plastering



Defects in the granite cladding for staircase walls

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

2/6

3/2/2022

C:\Users\o.naddaf\Desktop\QCs-02-2022\
QC- 211722022022.xlsx

Quality Control Report



Wrong level of the window sills



Corrosion appears on the steel protection screens

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Defects in the wall ceramic tiles cutting adjoining the door frames

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Rectified external plastering

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Rectified paint for the steel protection screens

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature