

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Um Al Dananir Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-11 19**
Date **21 / 05 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<ol style="list-style-type: none"> 1. Closing the gaps around the lighting fixtures and maintaining finishes around the sockets. 2. Broken edges of the granite of the landing floors. 3. Defects in installing the granite coping at the corridors and method of installation. 4. Installation of hinges for the swing doors at the corridors is not acceptable. 5. Defects in the beech wood frames for the wooden cabinets. 6. Open cleanouts and drains at the wet areas. 7. Wider gaps at the corners of the tiled wet areas. 8. Smaller dimensions for aluminum sections than required. 	<ol style="list-style-type: none"> 1. Close the gaps. 2. Replace. 3. Rectify. 4. Replace. 5. Replace defected frames. 6. Clean and keep covered. 7. Repair. 8. Rectify. 	<p>The Contractor/Immediately</p>

Report Prepared by

Hassan Shaqbua, Supervision
Quality Control Manager

Contractor's Response

The Contractor responded to remarks no.1, 2, 4 and 6.

Notes

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Gaps around the lighting fixtures



Broken edges of granite

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in granite coping



Unacceptable installation for door hinges

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in the beech wood frames



Open cleanouts and drains

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Wider gaps at the tiled wet areas



Smaller dimension for aluminum section

Consultant Site Engineer


Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Closing the gaps around the lighting fixtures

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Removing of defected granite tiles


Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Covering the cleanouts

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Reinstallation of the door hinges

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature