

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Jumana Bint Abi Taleb Basic Mixed - Marka**  
**Package** **Package 2**  
**Contractor** **Dijlah Est. Construction Co.**  
**Tender No.** **10/2019/USAID/SKEP/3/2**

**Rep No.** **QC-23 19**  
**Date** **5 / 06 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Defected stone at the canteen façade. 2. Defects in levelling of the interlock tiles at the yards. 3. Part of the main steel door does not comply with the architectural details. 4. Broken stone coping of the external walls. 5. Defected granite pieces for staircase cladding.	1. Replace. 2. Repair. 3. Replace the wrong section. 4. Replace. 5. Replace.	The Contractor/Immediately
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality Control Manager	
<b>Contractor's Response</b>		
The Contractor responded to remark no. (1) and (2)		
<b>Notes</b>		

Consultant Site Engineer


Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



**Defected stones at canteen façade**



**Defects in levelling of interlock tiles**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Door part does not comply with architectural details**



**Broken stone coping**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Defected granite pieces**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report

## Photos After:



**Replacement of defected stones**



**Repair of interlock tiles levelling**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature