

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Hay Al Iskan Basic mixed - Jerash**  
**Package** **Package 2**  
**Contractor** **Dijlah Est. Construction Co.**  
**Tender No.** **10/2019/USAID/SKEP/3/2**

**Rep No.** **QC-21 16**  
**Date** **2 / 01 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Defected granite pieces at the staircases. 2. Water penetration from the pump room at the roof to the ceiling of the top floor.	1. To be replaced. 2. To be replaced.	The Contractor/Immediately
<p align="center"><b>Report Prepared by</b></p>	Hassan Shaqbua, Supervision Quality Control Manager	
<p align="center"><b>Contractor's Response</b></p>		
No response yet		
<p align="center"><b>Notes</b></p>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos



**Defected granite for the staircases**



**Water penetration from the pumps room at the roof**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report

**Photos After:**



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature