

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Um Al Dananir Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-11 18**
Date **16 / 04 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Defects in the installed cabinets in the KG, beech wood frames, handle not vertical, broken partitions (laminated face). 2. In number of cabinets, the adjacent radiator prevents one cabinet door from opening completely. 3. Unprotected delivered door leafs. 4. Wrong dimensions to number of aluminum windows. 5. Broken ceramic at the wet areas. 6. The installed fire hose cabinets, the gap between the cabinet and the wall is not closed yet. 7. Storing the elevator equipment is inappropriate.	1. Repair. 2. Relocate radiator 20-30 cm far away. 3. Protect. 4. Replace. 5. Replace. 6. Close appropriately. 7. Store in an appropriate place.	The Contractor/Immediately

Report Prepared by

Hassan Shaqbua, Supervision
 Quality Control Manager

Contractor's Response

The Contractor responded to remark no. (1), (2) and (7).

Notes

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Defected cabinets

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defected cabinets

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defected cabinets

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Not complete opening



Unprotected door leafs

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Wrong dimension of aluminum sections

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Wrong dimension of aluminum sections



Broken ceramic tiles

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Gaps between the cabinet frame and the wall

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Inappropriate storage for the elevator equipment

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Removal of defected cabinets



Desmantling of radiator to allow opening to the cabinet

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

10/11

4/28/2022

C:\Users\o.naddaf\Desktop\Qc-New-April\QC-111816042022.xlsx

Quality Control Report



Installation of elevator



Installation of elevator

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature