

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Al Khansa'a Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-12 13**
Date **9 / 03 / 2022**

Description of Non-Conformance	Corrective Action	Required by / When
<ol style="list-style-type: none"> 1. The frame hangers of the suspended ceiling are not straight. 2. Defects in the beech wood frames for wooden doors. 3. Unlevelled thresholds at doors. 4. Broken window sills and observed dirt on some of them. 5. Previous remarks/defects in ceramic wall tiles. 	<ol style="list-style-type: none"> 1. Rectify. 2. Replace. 3. Rectify. 4. Rectify/Replace. 	The Contractor/without delay
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor responded and rectified previous remarks regarding defects in ceramic wall tiles at wet areas/remark no. (5)	
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Not straight frame hangers



Defects in beech wood frame

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

2/5

3/31/2022

C:\Users\o.naddaf\Desktop\new QCs-03-2022\
QC-121309032022.xlsx

Quality Control Report



Unlevelled threshold



Broken window sill

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Defects in installing wall tiles

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Removal of defected installed tiles



Re-tiling of ceramic wall tiles

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

5/5

3/31/2022

C:\Users\o.naddaf\Desktop\new QCs-03-2022\
QC-121309032022.xlsx