

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Um Al Dananir Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-11 09**
Date **29 / 07 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
The Chipping for the MEP installation is not done saw-cut using special cutting device.	Executed works should be rectified and the device should be used all over the work. The Contractor should submit method statement to rectify the defected works.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	

Contractor's Response		
No response yet		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Example of defected work

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Example of defected work

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Photos After: Not yet

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature