



Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Jumana Bint Abi Taleb Basic Mixed - Marka**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-23 09**
Date **6 / 10 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Ceramic tiling using tile adhesive failed in laboratory test.	Remove tiled area, provide adhesive with pass result.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor responded immediately.		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Removing of wall tiles due to the failure of adhesive material

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Re-tiling of wall tiles after replacing the adhesive material

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature