

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Al Khansa'a Basic Mixed - Balqa**  
**Package** **Package 1**  
**Contractor** **Derar Saraireh & Sons for Engineering & Contracting**  
**Tender No.** **1/2020/USAID/SKEP/3/1**

**Rep No.** **QC-12 07**  
**Date** **27 / 09 / 2021**

Description of Non-Conformance	Corrective Action	Required by / When
1. Installing door frames not complying with the required dimensions.	1. Remove the installed frames and replace with frames with the right dimensions.	The Contractor/Immediately
<p align="center"><b>Report Prepared by</b></p>	Hassan Shaqbua, Supervision Quality Control Manager	
<p align="center"><b>Contractor's Response</b></p>		
<p align="center"><b>Notes</b></p>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



First stage of replacing defected frames

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

**Photos After:**



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature